NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 1858

Customer: PRICON MICROELECTRONICS INC Date: 3 / 19 / 2019

Model: FE80S12H Machine no. 16 Mfg. yy/mm: 1995 3

Serial Number: P08Q011 Gts.: 3145975

Controller: N93C M/C Service Requested By: SIR RAFFY

Reason for Service / Machine Problem

- BLACKED OUT MONITOR DURING EJT. FORWARD
- ERROR [35]

Action Taken

- CHECKED ACTUAL M/C STATUS
- M/C OK DURING INJ FWD & BWD, MOLD OPEN/CLOSE; BUT DURING EJT FORWARD : MONITOR ERROR
- CHECKED EJECTOR CABLE CONNECTION (ENCODER)
- WIPED OIL ON OPTICAL CABLE
- CHECKED MACHINE PARAMETER ; UPON CHECKING PARAMETERS FOUND OUT THAT EV2 CHG IS GREATER THAN THE FWD STOP SETTING: EV2 CHG = 60 mm
  FWD STOP - 45 mm
- CHANGED EV2 CHG VALUE
- TRIED EJECTOR FWD ; MACHINE OK
- CONDUCTED BACKFLOW CHECKING ; WITH BACKFLOW

SERVICE BY:

1 A. ALMANZA 3 _____

2 R. BANTON 4 _____

TIME:

Start	End
10 : 15	11 : 45

Total: 1 hrs. 30 mins.

RIDDIE [illegible]
Authorized Customer Name & Signature

Service Fee: Php 7,000

Recommendation/Parts for Quotation

TORPEDO SET