NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2447

Customer: PRICON MICRO ELECTRONICS INC **Date:** 01 / 22 / 20

Model: NEX 50 III - 5EG **Machine no.** 22A **Mfg. yy/mm:** 2016. 03

Serial Number: H105150961K1 **Gts.:** 6728819

Controller: TACT IV **M/C Service Requested By:** SIR RAFFY / SIR ARNOLD

Reason for Service / Machine Problem	
072 EC: MOV. MOLD / LOWER LIMIT DEVIATION ALRM.	072 FB: MOV. MOLD / HEATER 2 STICKING
072F9: MOV. MOLD / HEATER 2 BROKEN	072FA: MOV. MOLD / HEATER 1 STICKING
072F8: MOV. MOLD / HEATER 1 BROKEN	
0736C: STA. MOLD / LOWER LIMIT DEV. ALRM.	

Action Taken

> CHECK ALL FUZE FOUND OUT 1 FUZE BUSTED
> CHECK THE AC SUPPLY OF CONTACTOR - OKAY HAVE
> CHECK THE MOLD HEATER CONNECTION FROM SSR TO AUX. SOCKET THEN NO CONNECTION GROUNDED
> THEN TRY TO CONNECT MOLD HEATER TO AUX. CONNECTION THEN MOLD HEATER "ON" SUDDENLY THE 1 FUZE HAD BEEN BUSTED
> WE TRY TO CHANGE NEW MOLD HEATER THEN INTERCHANGE SSR
> HEAT UP OKAY
> ~~FOUND~~ FOUND OUT ALSO "BREAK ALARM" SETTINGS ON CONTROL HAD BEEN CHANGE. ~~BACK TO ZERO~~
> CHANGE / BACK TO ZERO
* NISSEI RECOMMEND DON'T CHANGE OR CONDUCT UN-NECCESSARY CHANGE ON SETTINGS OR PARAMETERS

SERVICE BY:

1 R. BANTON 3 _____

2 F. CHING 4 _____

A.P. Martin
Authorized Customer Name & Signature

TIME:

Start	End
11 : 30	16 : 00

Total: 4 hrs. 30 mins.

Service Fee: Php 10,000.00

Recommendation/Parts for Quotation

m/c no. 24 NEX 50 III - 5EG
H105161001K1
TACT IV
2017. 04
* NOTE: 36 16650
THIS MACHINE CAN PROCEED FROM MASS PRODUCTION