NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2585

Customer: PRICON MICROELECTRONICS INC. **Date:** 07 / 01 / 20

Model: PN40-5H **Machine no.** 6A **Mfg. yy/mm:** 2004.9

Serial Number: P042011 **Gts.:** 10536803

Controller: NC93OOT **M/C Service Requested By:** SIR ALJHON

Reason for Service / Machine Problem	
MACHINE CHECKING DUE TO DROOLING ON MANUAL MODE	PN40-5H P042009 NC93OOT 2004.9

Action Taken

> CHECKED ACTUAL MONITOR DURING SCREW BWD IF KEEP BUT CONTINUE FWD. ~~FIRST~~ A
> FIRST ACTION INTERCHANGE BWD AND FWD SENSOR CABLE SAME PROBLEM
> THEN INTERCHANGE PRESSURE SWITCH OF BWD AND FWD (SCREW) SAME PROBLEM
> CHECKED ELECTRICAL FOR SENSOR 913 & 856, 915 AND 856 OKAY, CHECKED DURING AUTOMATIC SCREW POSITION, POSITION KEEP OKAY
> POSSIBLE PROBLEM SERVO VALVE LEAK INSIDE BUT PROBLEM NISSEI HAVE NO SPARE FOR THIS PART

SERVICE BY:

1 R. BANTON 3 _____

2 F. CHING 4 _____

Henry De Guzman

Authorized Customer Name & Signature

TIME:

Start	End
12 : 00	16 : 00

Total: 4 hrs. — mins.

Service Fee: Php 4,000.00

Recommendation/Parts for Quotation