NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2594

Customer: PRICON MICROELECTRONICS INC Date: 07 / 14 / 20

Model: PN60-5AN Machine no. 28 Mfg. yy/mm: 2009.3

Serial Number: N063107 Gts.: 5411219

Controller: TACT M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

MACHINE CANNOT SCREW BACKWARD

Action Taken

> CHECK DIAGNOS MONITOR
> CHECK BACKSCREEN DATA
> ~~LOAD~~ BORROW HYDRAULIC VALVE FROM OTHER MACHINE Y-243 (INJECTION DECOMPRESSION) BUT SAME PROBLEM
> CONDUCT MANUAL PUSH FROM HYDRAULIC VALVE BUT SAME PROBLEM
> CHECK INJECTION MOTOR OKAY NO HAVE DAMAGE
> CONDUCT MANUAL PUSH AT INJECTION RAM, OKAY EASY TO PUSH
> POSSIBLE PROBLEM SERVO VALVE

SERVICE BY:

1 R. BANTON 3 _____
2 F. CHING 4 _____

TIME:

Start	End
12 : 00	15 : 00

Total: 3 hrs. – mins.

AL JHON D. AÑONUEVO
Authorized Customer Name & Signature

Service Fee: Php N/A

Recommendation/Parts for Quotation

> SERVO VALVE