NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2597

Customer: PRICON MICRO ELECTRONICS INC Date: 07 / 14 / 20

Model: PN60 - 5AN Machine no. 28 Mfg. yy/mm: 2009. 3

Serial Number: N063107 Gts.: 5471219

Controller: TACT M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

MACHINE CANNOT SCREW BACKWARD

Action Taken

> CHECK FRONT AND BACKSCREEN DATA
> CHECKED DIAGNOS MONITOR
> CHECKED ELECTRIC SUPPLY 919 & 911, 919 & 912 ONLY -3.6V AND -2.3V
> TRY TO MANUAL PUSH HYDRAULIC VALVE BUT SAME PROBLEM
> CHANGE SERVO VALVE FROM CUSTOMER SPARE
> CONDUCT ~~FR~~ FUNCTION NOW SCREW CAN BACKWARD
> VOLTAGE OF 919 & 911 (0.9V) AND 919 & 912 (1.9V) NOW OKAY
> MACHINE CAN BE USE

SERVICE BY:

1 N. NISHIZAWA 3 R. BANTON
2 F. CHING 4

TIME:

Start	End
11 : 00	13 : 00

Total: 2 hrs. — mins.

Service Fee: Php 20,000.00

TOTAL SERVICE FEE TOGETHER WITH LAST TIME SERVICE REPORT A2594

ALJHON DO AÑONUEVO
Authorized Customer Name & Signature

Recommendation/Parts for Quotation

NISSEI RECOMMEND FOR SERVO VALVE TO BE OVERHAUL AT JAPAN, NISSEI WILL SEND FIRST QUOTATION