NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2756

Customer: PRICON MICRO ELECTRONICS INC

Date: 08 / 07 / 20

Model: FE80S12H Machine no. 16 Mfg. yy/mm: 1995.9

Serial Number: P08Q011 Gts.: 3403899

Controller: N93C M/C Service Requested By: SIR AL JOHN

Reason for Service / Machine Problem

b. N/C MOVEMENT ON CLAMPING, EJECTOR AND INJECTION UNIT.
b. 01247: LINE FILTER ALARM

Action Taken

1. CHECKED I/O SIGNAL ok.
2. CHECKED INTERLOCK ok.
3. CHECK OIL PUMP. ok.
4. REPLACED ANALOG BOARD SAME PROBLEM.
5. CHECKED PUMP AMPLIFIER FOUND NO POWER (24VDC)
6. REPLACED POWER SUPPLY (1-7) ok
7. TEST ALL FUNCTIONS ok.
8. FOUND TRIP: OFF MIS-SET FOR OIL CLEANER PUMP MOTOR - NG.
9. POSSIBLE PROBLEM ON OIL CLEANER PUMP MOTOR.
10. CUSTOMER BYPASS LINE FILTER SENSOR.
11. ERROR TUNING MONITOR BOOTING - I/F PROBLEM ON PASACON
12. MACHINE CAN STILL BE USE BY CUSTOMER.

SERVICE BY:

1 J. RUBIO 3

2 Y. RAMIREZ 4

TIME:

Start	End
14 : 30	17 : 30

Total: 3 hrs. mins.

SIR HENRY D. DE GUZMAN
Authorized Customer Name & Signature

Service Fee: Php 10,000

Recommendation/Parts for Quotation

1. POWER SUPPLY FOR PUMP AMPLIFIER
2. PASACON BOARD
3. OIL CLEANER PUMP MOTOR.
4. LINE FILTER.

NOTE:
> PARTS TEMPORARY BORROWED @ M/C #15 (24VDC POWER SUPPLY) 1-7