NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2838

Customer: PRICON MICROELECTRONICS INC Date: 11 / 24 / 20

Model: PN60 - 5AN Machine no. 28 Mfg. yy/mm: 2009. 3

Serial Number: N063107 Gts.: 5497593

Controller: TACT M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

PRODUCT SHORT SHOT

Action Taken

> CONDUCTED ~~SCRU~~ INJECTION PRESSURE AND SPEED CHECKING OKAY NO PROBLEM
> FOUND OUT DURING SEMI AUTO, SCREW NO ROTATION
> BORROW V23 (SCREW ROTATION) FROM MACHINE NO. 12A
> CONDUCT FUNCTION, NOW SCREW ROTATE DURING SEMI AUTO
> POSSIBLE PROBLEM HYDRAULIC VALVE V23

SERVICE BY:

1 R. BANTON 3 N. NISHIZAWA
2 F. CHING 4

ALJHON D. AÑONUEVO
Authorized Customer Name & Signature

TIME:

Start	End
13 :00	17 :00

Total: 4 hrs. - mins.

Service Fee: Php 14,000.00

Recommendation/Parts for Quotation

> HYDRAULIC VALVE (V23 SCREW ROTATE) 011 3E 128281
> NOZZLE