NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2882

Customer: PRICON MICROELECTRONICS, INC

Date: 12 / 14 / 20

Model: UH1000-80 Machine no. 14

Mfg. yy/mm: 1996.9

Serial Number: P08R010

Gts.: 6197950

Controller: 93T

M/C Service Requested By: SIR RAFFY

Reason for Service / Machine Problem

- 03216 : MIN OIL TEMP ERROR. ACCMLTR PRG. CHG PREHEAT
- 24007. TEMP CONTROLLER NO RESPONSE ERROR.
- ACCUMULATOR NOT CHARGING.

Action Taken

- FOUND NO ACTUAL VALUE ON HEATER AND OIL TEMPERATURE
- CHECKED PC BOARDS FOR LOOSE CONNECTION
- AFTER CHECKING TEMPERATURE OK.
- PUMP ON THEN ACCUMULATOR CHARGING.
- REPLACED OIL TEMP. CONTROLLER AND OPTIC CABLE
- TEST RUN WITH PRODUCT OK AGAIN
- FOR REPLACEMENT OF MONITOR DUE BLURRED DISPLAY

SERVICE BY:

1 J. RUBIO 3 _____

2 X. RAMIREZ 4 _____

TIME:

Start	End
15 : 00	16 : 30

Total: 1 hrs. 30 mins.

Service Fee: Php 7,000

LEANDER MORANDA

Authorized Customer Name & Signature

Recommendation/Parts for Quotation

- OPTIC CABLE
- MONITOR SET