NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 3029

Customer: PRICON MICROELECTRONICS INC Date: 03 / 10 / 21

Model: PN40 - 5H Machine no. 64 Mfg. yy/mm: 2004.9

Serial Number: P04Z011 Gts.: 10620798

Controller: NC93COT M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

53050: POSITION SENSOR COMMUNICATION LINE ERROR. 2

Action Taken

> UPON ARRIVAL CUSTOMER ALREADY INTERCHANGE CLAMPING ENCODER BUT SAME PROBLEM
> TRY TO CHANGE / INTERCHANGE SMALL CABLE, CONNECTED TO ENCODER (CLAMPING AND EJECTOR) TO CPU BOARD, BUT SAME PROBLEM
> CHECKED EJECTOR ENCODER CABLE, WHEN HAVE MOVEMENT, ALARM OCCUR, ~~NO~~ ALARM "23057: EJECTOR POSITION SENSOR NOT RESPOND" OCCUR
> CUT WIRE THEN RE-WIRE, ~~THE~~ ALARM CLEAR AFTER POWER ON

* WHEN CONDUCTING ~~MACHINE~~ MOVEMENT AT CLAMPING SIDE ALARM HAPPEN "53050: POSITION SENSOR COMMUNICATION LINE ERROR. 2" FOUND OUT EJECTOR ENCODER ~~NO GOOD~~ CABLE NO GOOD, DURING CHECKING FOUND OUT INSIDE CABLE WAS CUT

> FOR MONITORING

SERVICE BY:

1 F. CHING 3 _____
2 R. BARTON 4 _____

TIME:

Start	End
13 : 00	16 : 30

Total: 3 hrs. 30 mins.

ALJHON D. AÑONUEVO
Authorized Customer Name & Signature

Service Fee: Php 28,000.00

Recommendation/Parts for Quotation

> EJECTOR ENCODER CABLE
0352X196205 5.5M

> EJECTOR ENCODER (POS. SENSOR)
0352J063300 RHA0060A

* NOTE: TOTAL SERVICE FEE TOGETHER WITH PREVIOUS TROUBLESHOOTING FROM START TO FINISH