NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 3132

Customer: PRICON MICROELECTRONICS. Date: 05 / 14 / 21

Model: NH1000-80 Machine no. 13 Mfg. yy/mm: 1996.9

Serial Number: PC8R0009 Gts.: 9197278

Controller: 93T M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

- CUSTOMER ENCOUNTERED DOUBLE INJECT

Action Taken

- FOUND RESIN PRESSURE STILL VERY HIGH AFTER INJECT EVEN IN NEUTRAL POSITION
- REPLACED 212 & 214 VALVE BORROWED FROM OTHER MACHINE
- ADD FROM MACHINE /c
- CHECKED FUNCTION OK. PRESSURE DROP IN NEUTRAL POSITION
- RUNNING WITH PRODUCT o/c

SERVICE BY:

1 J. RUBIO 3 _____

2 _____ 4 _____

TIME:

Start	End
13 : 00	17 : 00

Total: 4 hrs. mins.

VINCE SALVACION
Authorized Customer Name & Signature

Service Fee: Php 13,000

Recommendation/Parts for Quotation

- V212 - SOLENOID VALVE
  0113E014800
  DG4V-3-2A-P7-H-50-JA1000
- V214 - LOGIC VALVE
  0H3LD14200
  LE40A10E
  LEV290