NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 3187

Customer: PRICON MICRO ELECTRONICS INC **Date:** 09 / 28 / 21

Model: PN60 - 5AN **Machine no.** 21A **Mfg. yy/mm:** 2010. 11

Serial Number: E0061000IK1 **Gts.:** 5713819

Controller: TACT **M/C Service Requested By:** SIR ALJHON

Reason for Service / Machine Problem

CANNOT FINISH ACC CHARGE

Action Taken

> CHECKED MACHINE
> TRY MANUAL PUSH / ~~F6~~ V102 (ACC HI PLOAD) BUT SAME PROBLEM
> TRY CHANGED NEW SPARE OF SHOCKLESS VALVE AND SOLENOID VALVE BUT SAME PROBLEM
> FOUND OUT ~~W~~ CONNECTION OF "964" TO RELAY FOR V250 (ACC DECOMP) WAS LOOSEN, FIXED THE CONNECTION / TIGHTEN
> TRY PUMP ON THEN ACC CHARGED FINISH
> MACHINE CAN BE USED
> ANOTHER PROBLEM ENCOUNTERED CANNOT ZERO RESET SCREW POSITION, FOUND OUT SENSOR FOR SCREW FWD AND BWD NO GOOD INSTALLATION, FIXED THE SENSOR ZERO RESET OKAY
> MACHINE CAN BE USE

SERVICE BY:

1 R. BANTON 3 N. NISHIZAWA
2 F. CHING 4

TIME:	
Start	End
15 : 00	17 :30

Total: 2 hrs. 30 mins.

ALJHON D. AÑONUEVO
Authorized Customer Name & Signature

Service Fee: Php 20,000.

Recommendation/Parts for Quotation

NOTE: TOTAL SERVICE FEE FROM START TO FINISH (INCLUDED LAST TIME TROUBLE SHOOT)