NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax: (049)544-5647

SERVICE REPORT

No.: A4005

Customer: PRICON MICROELECTRONICS Date: 06 / 3 / 22

Model: PN60-5AN Machine no. 21A Mfg. yy/mm: 2010.11

Serial Number: E0061000161 Gts.: 6378798

Controller: FACT M/C Service Requested By: SIR VINCE

Reason for Service / Machine Problem

1. DA201 : ORIGIN CORRECTION IS NOT COMPLETED.

Action Taken

1. REPLACED PRESSURE SENSOR (V500) BUT SAME PROBLEM
2. CHECKED ACCUMULATOR PRESSURE OK
3. FOUND OUT SENSOR FOR ORIGIN CORRECTION ~~IS~~ WAS MIS-PLUGH
4. ADJUSTED SENSOR
5. CONDUCTED CONFIRMATION O/C
6. MACHINE RUNNING WITH PRODUCT

SERVICE BY:

1 ~~ERIC~~ J. RUBIO 3 _____

2 X. RAMIREZ 4 _____

VINCE CALINGASAN
Authorized Customer Name & Signature

TIME:

Start	End
10 : 40	15 : 00

Total: 3 hrs. 20 mins.

Service Fee: PHP/JPY/USD 10,000.00

Recommendation/Parts for Quotation

Inclusive of Tax: ☐ Exclusive of Tax: ☐

TOTAL SERVICE FEE