NISSEI

NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax: (049)544-5647

SERVICE REPORT

No.: A4294

Customer: PRICON MICRO ELECTRONICS INC
Date: 12 / 01 / 22
Model: UH1000-80
Machine no. 14
Mfg. yy/mm: 1996.09
Serial Number: P08R010
Gts.: 6852654
Controller: 93T
M/C Service Requested By: SIR VINCE / SIR HENRY

Reason for Service / Machine Problem

"RE-CHECKING OF MACHINE SCREW BACKFLOW"
[SINKMARK PROBLEM ON PRODUCT]

Action Taken

>CONDUCT BACKFLOW TESTING: INJ. SPEED - 160mm/s
PRESSURE - 500kg/cm²
SM - 100mm
> 30 secs. HOLDING
ACTUAL - 11mm
(MATERIAL: DES / SGP2021R)
>FAILED ON BACKFLOW CHECKING / TESTING
> CONDUCT PRODUCT TRIAL; ADJUSTMENT ON MOLDING CONDITION PARAMETERS
> PRODUCT DEFECTS INCONSISTENT AFTER ADJUSTMENT ON PARAMETERS
> SEE RECOMMENDATION FOR MACHINE

SERVICE BY:

1 Y. RAMIREZ
2 J. RUBIO
3 N. NISHIZAWA
4

TIME:

Start	End
10 : 00	14 : 00

Total: 3 hrs. – mins.

Henry De Guzman
Authorized Customer Name & Signature

Service Fee: [✓ PHP]/JPY/USD 13,000.00

Recommendation/Parts for Quotation

Inclusive of Tax: ☐ Exclusive of Tax: ☐

>FOR CHECKING OF ACTUAL DIAMETER:
- SCREW/CHECK RING
- BARREL CYLINDER INSIDE DIAMETER

>REPLACEMENT OF TORPEDO SET (CHECK RING/TORPEDO/SEAT RING)
THAN CONDUCT PRODUCT TRIAL AGAIN

SERVICE FEE TOTAL OF TWO (2) MACHINE