

DAILY DRILLING REPORT (SYNTHETIC)

OIL-CHR-011 - Charali-011

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Charali / Girujan
Report Timestamp	2012-03-19 18:00:00
Current Depth	2121.0 m
Mud System	PHPA Water-Based Mud
Well Risk	Low (40.7/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
03-14 20:00	2016	2777	276	103	10.81	827/746	13.4	Event
03-15 09:06	2028	2773	204	111	10.85	813/801	8.6	Recovery
03-15 22:13	2040	2815	204	118	10.85	790/809	16.0	Normal
03-16 11:20	2051	2805	246	110	10.93	783/804	9.7	Normal
03-17 00:26	2063	2813	227	108	10.72	840/850	10.9	Normal
03-17 13:33	2075	2832	252	106	10.82	843/812	10.4	Normal
03-18 02:40	2086	2830	238	104	10.91	747/741	11.3	Normal
03-18 15:46	2098	3044	238	99	10.62	787/791	15.8	Normal
03-19 04:53	2109	2918	250	94	10.98	803/801	10.4	Normal
03-19 18:00	2121	2950	236	116	10.74	755/732	7.4	Normal

Operational Events / Lessons

Stuck Pipe (High) at 1293 m: Stuck Pipe at 1293 m in Girujan. Hookload became erratic during pipe movement. Stopped drilling and circulated bottoms-up. Outcome: Torque/drag returned toward baseline. Torque 284 kNm, drag 28.1 t, ROP 7.5 m/h. Recommended action: Plan preventive wiper trip near analogous interval

Cementing Issue (Critical) at 1305 m: Cementing Issue at 1305 m in Girujan. Displacement pressure became unstable. Extended observation of returns before concluding job. Outcome: Job completed with adjusted displacement plan. Cement returns 56% with density 15.73 ppg. Recommended action: Alert when cement-return percentage drops below expected envelope

Mud Loss (Medium) at 1450 m: Mud Loss at 1450 m in Girujan. Active pit volume declined during stable pump rate. Stopped drilling and performed flow check. Outcome: Full returns restored and drilling resumed. Flow balance: 726/666 LPM (in/out); pit change -8.3 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

Mud Loss (Medium) at 2016 m: Mud Loss at 2016 m in Girujan. Active pit volume declined during stable pump rate. Reduced pump rate and monitored active pits. Outcome: Circulation stabilized after treatment. Flow balance: 827/746 LPM (in/out); pit change -9.5 bbl. Recommended action: Monitor pit volume continuously within +/-50 m of this depth

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.