

DAILY DRILLING REPORT (SYNTHETIC)

OIL-DRK-004 - Dirok-004

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Dirok / Girujan
Report Timestamp	2013-08-03 18:00:00
Current Depth	2147.0 m
Mud System	Glycol-PHPA WBM
Well Risk	Moderate (46.4/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
07-30 09:36	2090	3043	232	106	11.14	785/770	12.5	Normal
07-30 21:12	2096	2730	247	106	10.84	867/837	7.4	Normal
07-31 08:48	2102	2669	234	109	10.89	797/778	6.1	Normal
07-31 20:24	2109	2729	231	109	10.77	818/813	9.6	Normal
08-01 08:00	2115	2856	229	101	10.94	777/783	8.6	Normal
08-01 19:36	2122	2840	228	115	10.89	752/759	8.5	Normal
08-02 07:12	2128	2681	243	105	10.96	733/725	13.1	Normal
08-02 18:48	2134	2741	236	107	11.01	772/802	13.9	Normal
08-03 06:24	2141	2816	242	101	10.77	766/773	10.8	Normal
08-03 18:00	2147	2879	242	100	11.15	780/758	7.4	Normal

Operational Events / Lessons

Fishing Operation (Medium) at 1665 m: Fishing Operation at 1665 m in Girujan. Mechanical obstruction prevented normal drilling progression. Confirmed fish top and planned engagement method. Outcome: Fish recovered and hole conditioned. Recommended action: Keep offset fishing history visible to BHA planning team

Mud Loss (Low) at 1730 m: Mud Loss at 1730 m in Girujan. Intermittent circulation losses developed while drilling ahead. Reduced pump rate and monitored active pits. Outcome: Full returns restored and drilling resumed. Flow balance: 778/789 LPM (in/out); pit change -3.8 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

Mud Loss (High) at 1756 m: Mud Loss at 1756 m in Girujan. Partial returns observed at shale shaker. Prepared graded lost-circulation pill. Outcome: Circulation stabilized after treatment. Flow balance: 751/611 LPM (in/out); pit change -12.6 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

Mud Loss (Low) at 1762 m: Mud Loss at 1762 m in Girujan. Flow-out dropped below flow-in with pit loss. Stopped drilling and performed flow check. Outcome: Circulation stabilized after treatment. Flow balance: 799/717 LPM (in/out); pit change -7.7 bbl. Recommended action: Reduce pump rate/ECD before entering analogous interval

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.