

DAILY DRILLING REPORT (SYNTHETIC)

OIL-GLK-009 - Geleki-009

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Geleki / Tipam
Report Timestamp	2005-02-25 18:00:00
Current Depth	2211.0 m
Mud System	Low-Solids WBM
Well Risk	Low (42.1/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
02-20 21:33	2112	2830	218	110	10.75	760/752	14.6	Normal
02-21 10:29	2123	2868	228	108	10.95	807/841	7.6	Normal
02-21 23:25	2134	2868	229	113	10.91	719/668	7.8	Normal
02-22 12:22	2145	2964	213	110	10.91	752/744	7.5	Normal
02-23 01:18	2156	2831	212	120	10.84	754/763	11.9	Normal
02-23 14:14	2167	2813	241	108	10.85	788/787	12.1	Normal
02-24 03:11	2178	2775	221	97	10.92	782/763	17.3	Normal
02-24 16:07	2189	2981	207	103	11.28	748/752	11.5	Normal
02-25 05:03	2200	2770	246	116	10.83	700/702	14.0	Normal
02-25 18:00	2211	2866	227	123	11.09	766/754	10.0	Normal

Operational Events / Lessons

Mud Loss (Low) at 1498 m: Mud Loss at 1498 m in Tipam. Intermittent circulation losses developed while drilling ahead. Reduced ROP and conditioned the hole. Outcome: Full returns restored and drilling resumed. Flow balance: 684/662 LPM (in/out); pit change -7.2 bbl. Recommended action: Reduce pump rate/ECD before entering analogous interval

Torque Spike (Medium) at 1757 m: Torque Spike at 1757 m in Tipam. Torque rose without corresponding pressure anomaly. Reamed short interval and circulated cuttings. Outcome: Torque returned to operating band after parameter change. Torque 333 kNm, drag 15.4 t, ROP 13.6 m/h. Recommended action: Reduce WOB/RPM proactively near correlated torque-spike depth

Fishing Operation (High) at 2068 m: Fishing Operation at 2068 m in Tipam. BHA retrieval required specialized tools. Confirmed fish top and planned engagement method. Outcome: Operation completed and BHA configuration reviewed. Recommended action: Escalate prolonged stuck-pipe events before mechanical failure

Stuck Pipe (Medium) at 2090 m: Stuck Pipe at 2090 m in Tipam. Hookload became erratic during pipe movement. Stopped drilling and circulated bottoms-up. Outcome: BHA freed and hole conditioned before drilling resumed. Torque 286 kNm, drag 28.0 t, ROP 7.5 m/h. Recommended action: Trigger stuck-pipe warning on combined torque/drag/ROP deterioration

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.