

DAILY DRILLING REPORT (SYNTHETIC)

OIL-HPJ-003 - Hapjan-003

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Hapjan / Girujan
Report Timestamp	2005-02-25 18:00:00
Current Depth	1968.0 m
Mud System	Low-Solids WBM
Well Risk	Moderate (52.0/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
02-21 06:54	1902	2710	239	104	10.82	778/758	7.7	Normal
02-21 18:48	1910	2579	256	99	10.72	747/730	9.3	Normal
02-22 06:42	1917	2608	244	121	10.85	761/770	13.5	Normal
02-22 18:36	1924	2820	216	106	10.61	773/764	9.7	Normal
02-23 06:30	1932	2707	273	111	10.80	780/793	10.4	Normal
02-23 18:24	1939	2798	232	107	10.79	746/745	11.3	Normal
02-24 06:18	1946	2660	194	106	10.68	810/834	9.4	Normal
02-24 18:12	1954	2759	229	115	10.87	732/714	10.3	Normal
02-25 06:06	1961	2708	214	108	10.61	799/793	11.1	Normal
02-25 18:00	1968	2492	225	103	10.53	743/742	7.0	Normal

Operational Events / Lessons

Cementing Issue (Low) at 1482 m: Cementing Issue at 1482 m in Girujan. Cement density/returns trend indicated placement uncertainty. Recorded pressure-volume response for remedial decision. Outcome: Job completed with adjusted displacement plan. Cement returns 22% with density 15.58 ppg. Recommended action: Use pressure-volume reconciliation during displacement

Stuck Pipe (High) at 1557 m: Stuck Pipe at 1557 m in Girujan. Rotary movement deteriorated progressively. Worked pipe within safe operating limits. Outcome: Pipe movement restored after circulation and working. Torque 309 kNm, drag 30.7 t, ROP 5.9 m/h. Recommended action: Trigger stuck-pipe warning on combined torque/drag/ROP deterioration

NPT (High) at 1683 m: NPT at 1683 m in Girujan. ROP dropped to zero during equipment unavailability. Switched to standby system where available. Outcome: Equipment restored and drilling resumed. Recommended action: Flag repeated downtime patterns before mobilization

Stuck Pipe (High) at 1822 m: Stuck Pipe at 1822 m in Girujan. Hookload became erratic during pipe movement. Reduced WOB and increased hole-cleaning circulation. Outcome: Restriction cleared without fishing operation. Torque 328 kNm, drag 33.4 t, ROP 7.0 m/h. Recommended action: Increase hole-cleaning surveillance before this depth

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.