

DAILY DRILLING REPORT (SYNTHETIC)

OIL-LKW-006 - Lakwa-006

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Lakwa / Kopili
Report Timestamp	2004-03-23 18:00:00
Current Depth	3560.0 m
Mud System	Glycol-PHPA WBM
Well Risk	Critical (66.9/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
03-19 02:01	3408	3796	324	107	12.03	762/752	7.4	Normal
03-19 14:27	3425	3881	332	124	12.07	777/766	11.4	Normal
03-20 02:54	3442	3853	290	109	12.06	786/803	14.1	Normal
03-20 15:20	3459	3862	298	122	12.21	804/794	11.6	Normal
03-21 03:47	3476	3638	323	106	12.26	825/829	14.7	Normal
03-21 16:13	3492	3923	305	110	12.16	722/709	10.7	Operational Variation
03-22 04:40	3509	3803	288	114	12.40	842/860	9.2	Normal
03-22 17:06	3526	4004	339	113	12.36	776/821	9.6	Operational Variation
03-23 05:33	3543	3872	305	109	12.21	793/780	10.2	Normal
03-23 18:00	3560	3775	335	106	12.66	806/840	14.3	Normal

Operational Events / Lessons

Stuck Pipe (High) at 2742 m: Stuck Pipe at 2742 m in Kopili. Torque and drag increased while ROP declined. Back-reamed cautiously while monitoring torque. Outcome: Torque/drag returned toward baseline. Torque 412 kNm, drag 36.9 t, ROP 5.4 m/h. Recommended action: Trigger stuck-pipe warning on combined torque/drag/ROP deterioration

Cementing Issue (Medium) at 2846 m: Cementing Issue at 2846 m in Kopili. Displacement pressure became unstable. Reduced displacement rate and monitored returns. Outcome: Job completed with adjusted displacement plan. Cement returns 22% with density 14.83 ppg. Recommended action: Alert when cement-return percentage drops below expected envelope

Pressure Spike (High) at 3034 m: Pressure Spike at 3034 m in Kopili. Pressure trend exceeded recent moving baseline. Reduced pump rate and checked circulation response. Outcome: Restriction cleared without further escalation. SPP 4652 psi at flow-in 766 LPM. Recommended action: Compare SPP against offset-well envelope at equivalent depth

NPT (Low) at 3272 m: NPT at 3272 m in Kopili. Drilling parameters were stable but operations were suspended. Recorded downtime cause and maintenance action. Outcome: Equipment restored and drilling resumed. Recommended action: Track recurring NPT cause by rig and equipment family

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.