

DAILY DRILLING REPORT (SYNTHETIC)

OIL-MRN-008 - Moran-008

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Moran / Girujan
Report Timestamp	2000-07-10 18:00:00
Current Depth	2358.0 m
Mud System	Low-Solids WBM
Well Risk	Low (37.0/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
07-05 16:02	2286	2926	247	98	11.13	814/836	15.8	Normal
07-06 05:35	2294	2881	228	101	11.11	809/788	12.6	Normal
07-06 19:08	2302	3018	249	106	11.03	776/795	14.1	Normal
07-07 08:41	2310	3006	285	103	11.15	856/855	11.7	Normal
07-07 22:14	2318	3170	226	105	11.10	754/749	12.2	Normal
07-08 11:47	2326	2993	258	118	11.06	780/772	13.9	Normal
07-09 01:20	2334	2954	260	107	11.17	735/718	10.8	Normal
07-09 14:53	2342	2958	312	110	11.13	777/782	10.7	Normal
07-10 04:26	2350	2904	262	97	10.86	742/715	11.0	Normal
07-10 18:00	2358	3038	205	105	11.10	718/726	12.6	Normal

Operational Events / Lessons

Torque Spike (High) at 1355 m: Torque Spike at 1355 m in Girujan. Sharp torque excursion occurred with RPM instability. Adjusted rotary parameters and observed response. Outcome: Torque returned to operating band after parameter change. Torque 381 kNm, drag 12.4 t, ROP 17.1 m/h. Recommended action: Reduce WOB/RPM proactively near correlated torque-spike depth

Kick (Medium) at 1842 m: Kick at 1842 m in Girujan. Drilling break followed by positive flow check. Shut in well and recorded pressures. Outcome: Gas trend returned to baseline. Gas 153 units; pit change +11.9 bbl; mud weight 10.56 ppg. Recommended action: Raise kick advisory when flow-out exceeds flow-in with rising gas

Cementing Issue (High) at 1981 m: Cementing Issue at 1981 m in Girujan. Displacement pressure became unstable. Recorded pressure-volume response for remedial decision. Outcome: Returns improved after rate reduction. Cement returns 28% with density 15.44 ppg. Recommended action: Alert when cement-return percentage drops below expected envelope

Cementing Issue (Low) at 1989 m: Cementing Issue at 1989 m in Girujan. Cement density/returns trend indicated placement uncertainty. Verified volumes and adjusted cementing rate. Outcome: Cementing sequence stabilized within revised limits. Cement returns 50% with density 14.77 ppg. Recommended action: Review nearby loss events before finalizing cement program

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.