

DAILY DRILLING REPORT (SYNTHETIC)

OIL-NHK-008 - Nahorkatiya-008

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Nahorkatiya / Kopili
Report Timestamp	2020-02-02 18:00:00
Current Depth	3270.0 m
Mud System	Low-Solids WBM
Well Risk	High (59.1/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
01-27 23:53	3153	3637	301	110	11.88	761/761	13.7	Normal
01-28 15:14	3166	3543	308	98	11.89	754/755	11.7	Normal
01-29 06:35	3179	3638	276	121	11.86	790/791	13.6	Operational Variation
01-29 21:55	3192	3666	285	110	11.79	806/816	13.1	Normal
01-30 13:16	3205	3581	333	106	11.87	737/734	10.4	Normal
01-31 04:37	3218	3560	288	115	11.81	783/774	9.4	Normal
01-31 19:57	3231	3696	412	118	11.91	800/787	13.3	Operational Variation
02-01 11:18	3244	3682	306	100	11.90	801/784	11.8	Normal
02-02 02:39	3257	3675	292	109	12.08	723/721	11.6	Normal
02-02 18:00	3270	3915	261	111	12.04	752/725	9.1	Normal

Operational Events / Lessons

Cementing Issue (High) at 1944 m: Cementing Issue at 1944 m in Kopili. Observed returns did not match calculated displacement. Extended observation of returns before concluding job. Outcome: Returns improved after rate reduction. Cement returns 50% with density 16.79 ppg. Recommended action: Alert when cement-return percentage drops below expected envelope

Fishing Operation (Medium) at 2106 m: Fishing Operation at 2106 m in Kopili. BHA retrieval required specialized tools. Suspended drilling while recovery operation was executed. Outcome: Retrieval completed with recorded NPT impact. Recommended action: Review BHA reliability near correlated problematic interval

Kick (Low) at 2495 m: Kick at 2495 m in Kopili. Unexpected background gas rise preceded influx. Circulated influx under controlled conditions. Outcome: Influx circulated out and overbalance restored. Gas 170 units; pit change +5.6 bbl; mud weight 11.22 ppg. Recommended action: Raise kick advisory when flow-out exceeds flow-in with rising gas

NPT (Low) at 2575 m: NPT at 2575 m in Kopili. Rotary and WOB remained at zero during downtime. Performed checks before restarting operations. Outcome: System returned to service within revised plan. Recommended action: Track recurring NPT cause by rig and equipment family

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.