

DAILY DRILLING REPORT (SYNTHETIC)

OIL-NHK-011 - Nahorkatiya-011

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Nahorkatiya / Girujan
Report Timestamp	2021-08-10 18:00:00
Current Depth	2369.0 m
Mud System	KCl Polymer WBM
Well Risk	Moderate (47.0/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
08-05 19:37	2217	2953	267	114	10.97	760/785	7.4	Normal
08-06 08:47	2234	2924	246	101	11.01	791/846	8.3	Normal
08-06 21:56	2251	3109	261	113	10.91	803/782	14.3	Normal
08-07 11:05	2268	3040	229	95	10.98	750/754	14.0	Normal
08-08 00:14	2285	2894	242	101	11.25	835/851	14.5	Normal
08-08 13:23	2302	3054	236	110	11.24	778/808	9.3	Normal
08-09 02:32	2318	2921	273	106	11.25	762/741	12.2	Normal
08-09 15:41	2335	3053	220	113	11.09	777/769	6.9	Normal
08-10 04:50	2352	3125	226	120	11.20	745/729	12.7	Normal
08-10 18:00	2369	2978	246	117	11.23	786/766	10.0	Normal

Operational Events / Lessons

Pressure Spike (Low) at 1858 m: Pressure Spike at 1858 m in Girujan. Circulating pressure climbed without equivalent torque change. Conditioned hole before restoring flow rate. Outcome: Standpipe pressure normalized after circulation. SPP 3019 psi at flow-in 794 LPM. Recommended action: Alert on sustained SPP deviation at constant flow

Stuck Pipe (High) at 1961 m: Stuck Pipe at 1961 m in Girujan. High drag was recorded while circulating remained possible. Worked pipe within safe operating limits. Outcome: Torque/drag returned toward baseline. Torque 256 kNm, drag 26.0 t, ROP 4.7 m/h. Recommended action: Plan preventive wiper trip near analogous interval

Mud Loss (Medium) at 1978 m: Mud Loss at 1978 m in Girujan. Active pit volume declined during stable pump rate. Prepared graded lost-circulation pill. Outcome: Full returns restored and drilling resumed. Flow balance: 802/592 LPM (in/out); pit change -11.2 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

Mud Loss (High) at 1996 m: Mud Loss at 1996 m in Girujan. Intermittent circulation losses developed while drilling ahead. Stopped drilling and performed flow check. Outcome: Full returns restored and drilling resumed. Flow balance: 763/572 LPM (in/out); pit change -12.0 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.