

DAILY DRILLING REPORT (SYNTHETIC)

OIL-RDS-001 - Rudrasagar-001

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Rudrasagar / Girujan
Report Timestamp	2007-01-19 18:00:00
Current Depth	2302.0 m
Mud System	Glycol-PHPA WBM
Well Risk	Low (34.5/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
01-15 02:04	2228	3111	225	103	10.82	780/782	9.3	Normal
01-15 14:30	2236	2952	281	115	11.10	797/795	10.9	Normal
01-16 02:57	2244	2770	241	104	11.07	818/767	10.3	Normal
01-16 15:23	2252	3012	246	98	10.96	740/723	8.7	Normal
01-17 03:49	2261	2878	244	103	11.11	744/749	17.1	Normal
01-17 16:15	2269	2769	234	113	10.99	774/780	10.1	Normal
01-18 04:41	2277	3085	250	112	10.89	788/770	9.2	Normal
01-18 17:07	2286	2970	217	106	10.93	788/795	9.3	Normal
01-19 05:33	2294	2904	230	110	11.09	775/782	11.6	Normal
01-19 18:00	2302	3054	281	104	10.97	795/789	12.5	Normal

Operational Events / Lessons

NPT (Medium) at 1539 m: NPT at 1539 m in Girujan. ROP dropped to zero during equipment unavailability. Switched to standby system where available. Outcome: Equipment restored and drilling resumed. Recommended action: Flag repeated downtime patterns before mobilization

Mud Loss (Critical) at 1844 m: Mud Loss at 1844 m in Girujan. Flow-out dropped below flow-in with pit loss. Stopped drilling and performed flow check. Outcome: Loss rate reduced to acceptable level. Flow balance: 772/660 LPM (in/out); pit change -11.4 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

Mud Loss (Medium) at 1978 m: Mud Loss at 1978 m in Girujan. Partial returns observed at shale shaker. Prepared graded lost-circulation pill. Outcome: Interval drilled through with controlled losses. Flow balance: 761/701 LPM (in/out); pit change -2.5 bbl. Recommended action: Monitor pit volume continuously within +/-50 m of this depth

NPT (Low) at 2211 m: NPT at 2211 m in Girujan. Rotary and WOB remained at zero during downtime. Isolated equipment and initiated maintenance. Outcome: Equipment restored and drilling resumed. Recommended action: Use offset NPT history in operational readiness review

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.