

DAILY DRILLING REPORT (SYNTHETIC)

OIL-BGJ-008 - Baghjan-008

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Baghjan / Tipam
Report Timestamp	2010-04-25 18:00:00
Current Depth	2612.0 m
Mud System	KCl Polymer WBM
Well Risk	Low (36.0/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
04-20 16:25	2502	3241	241	107	11.30	762/778	11.8	Normal
04-21 05:56	2514	3229	251	95	11.14	741/734	10.9	Normal
04-21 19:26	2526	3137	211	105	11.31	807/796	12.1	Normal
04-22 08:57	2539	3224	270	116	11.27	802/793	10.7	Normal
04-22 22:27	2551	3131	235	103	11.39	715/725	9.9	Normal
04-23 11:58	2563	3247	267	113	11.37	781/779	9.4	Normal
04-24 01:28	2575	3077	246	118	11.30	732/740	13.9	Normal
04-24 14:59	2588	3214	252	101	11.51	748/754	12.7	Normal
04-25 04:29	2600	2991	231	113	11.25	705/692	14.0	Normal
04-25 18:00	2612	3156	274	109	11.42	758/743	10.7	Normal

Operational Events / Lessons

Kick (Medium) at 2207 m: Kick at 2207 m in Tipam. Pit gain and flow with pumps off were observed. Increased monitoring frequency and prepared kill-weight mud. Outcome: Influx circulated out and overbalance restored. Gas 102 units; pit change +10.6 bbl; mud weight 11.05 ppg. Recommended action: Raise kick advisory when flow-out exceeds flow-in with rising gas

Pressure Spike (Medium) at 2281 m: Pressure Spike at 2281 m in Tipam. Short-duration high-pressure excursion was recorded. Stopped drilling and circulated at controlled rate. Outcome: Hydraulics returned to baseline. SPP 3713 psi at flow-in 774 LPM. Recommended action: Reduce pump rate and verify circulation if pressure trend persists

Torque Spike (High) at 2318 m: Torque Spike at 2318 m in Tipam. Rotary speed fluctuated during constant pump rate. Paused drilling to verify BHA behaviour. Outcome: Rotary stability recovered after reaming. Torque 344 kNm, drag 16.5 t, ROP 10.5 m/h. Recommended action: Set warning on rapid torque rise with RPM instability

Stuck Pipe (Low) at 2453 m: Stuck Pipe at 2453 m in Tipam. Torque and drag increased while ROP declined. Back-reamed cautiously while monitoring torque. Outcome: Pipe movement restored after circulation and working. Torque 271 kNm, drag 29.3 t, ROP 4.9 m/h. Recommended action: Trigger stuck-pipe warning on combined torque/drag/ROP deterioration

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.