

DAILY DRILLING REPORT (SYNTHETIC)

OIL-BRH-005 - Borholla-005

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Borholla / Girujan
Report Timestamp	2010-05-10 18:00:00
Current Depth	2279.0 m
Mud System	PHPA Water-Based Mud
Well Risk	Low (35.5/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
05-05 07:10	2210	2959	213	111	11.01	747/759	10.7	Normal
05-05 21:42	2218	2870	229	119	11.00	815/839	15.3	Normal
05-06 12:14	2226	2912	245	108	11.18	793/816	9.7	Normal
05-07 02:47	2233	2970	300	117	10.91	824/833	11.8	Normal
05-07 17:19	2241	2966	236	114	11.05	727/738	11.6	Normal
05-08 07:51	2248	2969	267	103	10.91	727/747	9.2	Normal
05-08 22:23	2256	2853	193	118	10.98	719/749	8.8	Normal
05-09 12:55	2264	2972	229	95	11.16	711/665	12.2	Normal
05-10 03:27	2271	3019	251	111	11.12	777/783	11.4	Normal
05-10 18:00	2279	2981	269	108	10.93	700/686	11.3	Normal

Operational Events / Lessons

Cementing Issue (Medium) at 1925 m: Cementing Issue at 1925 m in Girujan. Cement returns were below planned percentage. Reduced displacement rate and monitored returns. Outcome: Placement completed with remedial monitoring recommendation. Cement returns 30% with density 15.07 ppg. Recommended action: Review nearby loss events before finalizing cement program

Cementing Issue (High) at 1933 m: Cementing Issue at 1933 m in Girujan. Cement returns were below planned percentage. Extended observation of returns before concluding job. Outcome: Returns improved after rate reduction. Cement returns 18% with density 13.77 ppg. Recommended action: Use pressure-volume reconciliation during displacement

Torque Spike (Medium) at 1979 m: Torque Spike at 1979 m in Girujan. Rotary speed fluctuated during constant pump rate. Reduced WOB and RPM. Outcome: Torque returned to operating band after parameter change. Torque 335 kNm, drag 13.3 t, ROP 11.4 m/h. Recommended action: Compare live torque derivative with offset-well baseline

Cementing Issue (Medium) at 2187 m: Cementing Issue at 2187 m in Girujan. Displacement pressure became unstable. Reduced displacement rate and monitored returns. Outcome: Returns improved after rate reduction. Cement returns 47% with density 14.56 ppg. Recommended action: Alert when cement-return percentage drops below expected envelope

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.