

DAILY DRILLING REPORT (SYNTHETIC)

OIL-BRH-008 - Borholla-008

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Borholla / Girujan
Report Timestamp	2019-09-17 18:00:00
Current Depth	1955.0 m
Mud System	Low-Solids WBM
Well Risk	Low (34.8/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
09-12 09:19	1894	2784	238	111	10.80	797/809	11.7	Normal
09-12 23:37	1901	2627	163	107	10.79	754/776	13.2	Normal
09-13 13:55	1908	2616	276	105	10.53	800/801	11.3	Normal
09-14 04:13	1914	2572	237	96	10.75	809/770	14.8	Normal
09-14 18:30	1921	2734	248	112	10.84	711/721	8.5	Normal
09-15 08:48	1928	2764	234	98	10.72	729/709	10.5	Normal
09-15 23:06	1935	2752	248	108	10.82	811/773	10.3	Normal
09-16 13:24	1942	2710	225	95	10.65	761/755	9.8	Normal
09-17 03:42	1948	2637	250	108	10.82	821/806	10.4	Normal
09-17 18:00	1955	2760	210	92	10.78	764/777	11.2	Normal

Operational Events / Lessons

Kick (Low) at 1436 m: Kick at 1436 m in Girujan. Flow-out exceeded flow-in and gas units increased. Increased monitoring frequency and prepared kill-weight mud. Outcome: Gas trend returned to baseline. Gas 120 units; pit change +5.2 bbl; mud weight 10.34 ppg. Recommended action: Set flow-check trigger for unexplained pit gain

Fishing Operation (High) at 1457 m: Fishing Operation at 1457 m in Girujan. Mechanical obstruction prevented normal drilling progression. Confirmed fish top and planned engagement method. Outcome: Recovered component and resumed drilling after inspection. Recommended action: Escalate prolonged stuck-pipe events before mechanical failure

Mud Loss (Medium) at 1588 m: Mud Loss at 1588 m in Girujan. Intermittent circulation losses developed while drilling ahead. Reduced ROP and conditioned the hole. Outcome: Full returns restored and drilling resumed. Flow balance: 746/630 LPM (in/out); pit change -7.9 bbl. Recommended action: Reduce pump rate/ECD before entering analogous interval

Fishing Operation (Critical) at 1615 m: Fishing Operation at 1615 m in Girujan. Downhole tool remained unrecovered after freeing attempts. Secured well and mobilized retrieval tools. Outcome: Recovered component and resumed drilling after inspection. Recommended action: Keep offset fishing history visible to BHA planning team

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.