

DAILY DRILLING REPORT (SYNTHETIC)

OIL-HPJ-004 - Hapjan-004

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Hapjan / Barail
Report Timestamp	2001-07-11 18:00:00
Current Depth	2819.0 m
Mud System	Low-Solids WBM
Well Risk	Moderate (53.2/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
07-07 18:42	2628	3220	251	105	11.68	740/723	10.0	Normal
07-08 05:17	2649	3259	317	103	11.66	795/740	7.4	Precursor
07-08 15:52	2670	3164	310	102	11.23	797/807	8.0	Precursor
07-09 02:28	2692	3354	360	97	11.49	825/786	8.0	Event
07-09 13:03	2713	3896	327	98	11.52	741/717	11.9	Recovery
07-09 23:38	2734	3460	238	111	11.55	809/827	11.6	Normal
07-10 10:14	2755	3270	252	108	11.51	739/761	8.6	Normal
07-10 20:49	2777	3250	268	109	11.72	782/810	13.3	Normal
07-11 07:24	2798	3277	245	103	11.68	709/696	5.2	Normal
07-11 18:00	2819	3477	271	99	11.60	740/749	4.7	Normal

Operational Events / Lessons

Mud Loss (High) at 2285 m: Mud Loss at 2285 m in Barail. Flow-out dropped below flow-in with pit loss. Reduced ROP and conditioned the hole. Outcome: Circulation stabilized after treatment. Flow balance: 729/563 LPM (in/out); pit change -9.9 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

Mud Loss (Medium) at 2371 m: Mud Loss at 2371 m in Barail. Partial returns observed at shale shaker. Prepared graded lost-circulation pill. Outcome: Full returns restored and drilling resumed. Flow balance: 711/638 LPM (in/out); pit change -5.6 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

NPT (Medium) at 2585 m: NPT at 2585 m in Barail. No depth progress occurred during the recorded interval. Performed checks before restarting operations. Outcome: Downtime closed with maintenance record. Recommended action: Track recurring NPT cause by rig and equipment family

Stuck Pipe (Medium) at 2692 m: Stuck Pipe at 2692 m in Barail. Torque and drag increased while ROP declined. Reduced WOB and increased hole-cleaning circulation. Outcome: Pipe movement restored after circulation and working. Torque 360 kNm, drag 31.6 t, ROP 8.0 m/h. Recommended action: Increase hole-cleaning surveillance before this depth

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.