

DAILY DRILLING REPORT (SYNTHETIC)

OIL-HPJ-006 - Hapjan-006

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Hapjan / Girujan
Report Timestamp	2014-07-18 18:00:00
Current Depth	2373.0 m
Mud System	KCl Polymer WBM
Well Risk	Moderate (55.7/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
07-13 10:02	2213	2833	216	107	10.98	833/849	8.0	Normal
07-14 00:15	2231	2915	223	108	10.91	818/849	8.7	Normal
07-14 14:28	2249	2905	273	105	10.99	824/818	6.1	Normal
07-15 04:41	2266	2857	228	105	11.03	850/844	12.6	Normal
07-15 18:54	2284	3008	261	103	10.92	799/809	9.4	Normal
07-16 09:07	2302	2872	246	108	10.92	770/772	13.9	Normal
07-16 23:20	2320	2818	201	114	11.08	716/679	10.5	Normal
07-17 13:33	2338	3037	302	106	11.08	797/796	7.3	Normal
07-18 03:46	2355	2983	238	102	10.96	791/807	12.2	Normal
07-18 18:00	2373	3017	248	98	11.01	796/807	11.6	Normal

Operational Events / Lessons

Mud Loss (High) at 1998 m: Mud Loss at 1998 m in Girujan. Active pit volume declined during stable pump rate. Reduced ROP and conditioned the hole. Outcome: Circulation stabilized after treatment. Flow balance: 855/706 LPM (in/out); pit change -6.5 bbl. Recommended action: Monitor pit volume continuously within +/-50 m of this depth

Kick (Medium) at 2106 m: Kick at 2106 m in Girujan. Unexpected background gas rise preceded influx. Circulated influx under controlled conditions. Outcome: Influx circulated out and overbalance restored. Gas 202 units; pit change +12.8 bbl; mud weight 10.80 ppg. Recommended action: Set flow-check trigger for unexplained pit gain

Torque Spike (Medium) at 2124 m: Torque Spike at 2124 m in Girujan. Torque rose without corresponding pressure anomaly. Paused drilling to verify BHA behaviour. Outcome: Spike cleared with no equipment damage. Torque 292 kNm, drag 12.0 t, ROP 11.9 m/h. Recommended action: Reduce WOB/RPM proactively near correlated torque-spike depth

NPT (Medium) at 2177 m: NPT at 2177 m in Girujan. Rotary and WOB remained at zero during downtime. Isolated equipment and initiated maintenance. Outcome: Equipment restored and drilling resumed. Recommended action: Track recurring NPT cause by rig and equipment family

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.