

DAILY DRILLING REPORT (SYNTHETIC)

OIL-KMC-008 - Kumchai-008

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Kumchai / Girujan
Report Timestamp	2024-07-24 18:00:00
Current Depth	2196.0 m
Mud System	KCl Polymer WBM
Well Risk	Moderate (45.2/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
07-20 10:18	2126	2613	275	120	11.01	822/808	7.5	Normal
07-20 21:49	2134	2778	245	102	10.78	794/815	11.4	Normal
07-21 09:20	2142	2743	274	116	11.03	741/723	9.9	Normal
07-21 20:52	2149	3158	206	101	10.79	741/762	9.5	Normal
07-22 08:23	2157	2847	260	119	10.88	730/752	8.8	Normal
07-22 19:54	2165	2967	220	107	10.82	734/729	13.9	Normal
07-23 07:26	2173	2733	254	109	10.78	748/753	11.0	Normal
07-23 18:57	2180	2970	206	104	11.00	729/701	12.1	Normal
07-24 06:28	2188	2927	244	103	11.09	788/790	4.9	Normal
07-24 18:00	2196	2955	239	110	10.83	774/776	12.3	Normal

Operational Events / Lessons

Kick (Medium) at 1662 m: Kick at 1662 m in Girujan. Flow-out exceeded flow-in and gas units increased. Shut in well and recorded pressures. Outcome: Influx circulated out and overbalance restored. Gas 179 units; pit change +9.7 bbl; mud weight 10.25 ppg. Recommended action: Set flow-check trigger for unexplained pit gain

Stuck Pipe (High) at 1750 m: Stuck Pipe at 1750 m in Girujan. Hookload became erratic during pipe movement. Reduced WOB and increased hole-cleaning circulation. Outcome: Restriction cleared without fishing operation. Torque 320 kNm, drag 38.3 t, ROP 3.5 m/h. Recommended action: Increase hole-cleaning surveillance before this depth

Stuck Pipe (Medium) at 1868 m: Stuck Pipe at 1868 m in Girujan. Rotary movement deteriorated progressively. Reduced WOB and increased hole-cleaning circulation. Outcome: Pipe movement restored after circulation and working. Torque 291 kNm, drag 30.1 t, ROP 6.7 m/h. Recommended action: Trigger stuck-pipe warning on combined torque/drag/ROP deterioration

Stuck Pipe (Medium) at 1946 m: Stuck Pipe at 1946 m in Girujan. Hookload became erratic during pipe movement. Reduced WOB and increased hole-cleaning circulation. Outcome: BHA freed and hole conditioned before drilling resumed. Torque 271 kNm, drag 27.8 t, ROP 4.4 m/h. Recommended action: Trigger stuck-pipe warning on combined torque/drag/ROP deterioration

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.