

DAILY DRILLING REPORT (SYNTHETIC)

OIL-RDS-002 - Rudrasagar-002

NWIS prototype document - not an Oil India Limited operational record

Field / Formation	Rudrasagar / Girujan
Report Timestamp	2006-05-23 18:00:00
Current Depth	1926.0 m
Mud System	PHPA Water-Based Mud
Well Risk	Low (31.5/100)
Latest Alert	Normal

Recent Drilling Parameters

Timestamp	Depth	SPP	Torque	RPM	MW	Flow In/Out	ROP	State
05-18 07:36	1875	2812	205	90	10.59	799/812	11.5	Normal
05-18 22:05	1880	2689	202	106	10.70	731/735	9.0	Normal
05-19 12:34	1886	2522	240	109	10.65	789/769	13.5	Normal
05-20 03:04	1892	2636	238	118	10.60	793/780	10.6	Normal
05-20 17:33	1898	2634	198	106	10.64	800/815	9.7	Normal
05-21 08:02	1903	2526	203	100	10.65	868/844	6.7	Normal
05-21 22:32	1909	2596	238	106	10.79	718/710	10.5	Normal
05-22 13:01	1915	2714	190	112	10.79	735/753	11.0	Normal
05-23 03:30	1920	2680	198	104	10.73	802/787	9.0	Normal
05-23 18:00	1926	2740	205	107	10.84	742/733	8.7	Normal

Operational Events / Lessons

Mud Loss (Medium) at 1443 m: Mud Loss at 1443 m in Girujan. Active pit volume declined during stable pump rate. Reduced ROP and conditioned the hole. Outcome: Full returns restored and drilling resumed. Flow balance: 698/575 LPM (in/out); pit change -10.7 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

Stuck Pipe (Critical) at 1449 m: Stuck Pipe at 1449 m in Girujan. Torque and drag increased while ROP declined. Reduced WOB and increased hole-cleaning circulation. Outcome: BHA freed and hole conditioned before drilling resumed. Torque 225 kNm, drag 29.9 t, ROP 3.7 m/h. Recommended action: Plan preventive wiper trip near analogous interval

Kick (Medium) at 1536 m: Kick at 1536 m in Girujan. Unexpected background gas rise preceded influx. Stopped drilling and performed flow check. Outcome: Operations resumed after well-control verification. Gas 131 units; pit change +11.4 bbl; mud weight 10.16 ppg. Recommended action: Review mud-weight margin 50 m before correlated kick depth

Mud Loss (Medium) at 1852 m: Mud Loss at 1852 m in Girujan. Flow-out dropped below flow-in with pit loss. Stopped drilling and performed flow check. Outcome: Circulation stabilized after treatment. Flow balance: 751/690 LPM (in/out); pit change -3.1 bbl. Recommended action: Pre-stage LCM and set early-warning threshold on flow-out deficit

This DDR is generated from synthetic telemetry for OCR/NLP/RAG and risk-engine prototyping.