

Troubleshooting Guide: Emergency Diesel Generator — Fuel Water Contamination Causing Low Fuel Pressure Trips

Category: Utilities / Emergency Power / Fuel Systems **Unit:** Emergency Diesel Generator, Fuel Supply System (Day Tank, Filter/Coalescer) **Tools:** Fuel water content (Karl Fischer) trending, filter differential pressure trend review **Fluid Package:** Not applicable — this is a fuel quality/water separation investigation, not a phase-equilibrium simulation **Symptom:** Intermittent low fuel pressure trips during generator testing and operation

1. Quick Reference

Item	Detail
Reported symptom	Intermittent low fuel pressure trips occurring during routine generator testing/operation
Initially unclear	Whether this was a fuel pump mechanical issue, a filter fouling issue, or a fuel quality (water contamination) issue
Actual root cause	The day tank's water drain float valve had failed, allowing water to accumulate and periodically slug into the fuel filter/coalescer, overwhelming its water separation capacity and triggering low fuel pressure trips
Fix	Repaired/replaced the water drain valve; drained accumulated water from the day tank; replaced fouled filter elements
Diagnostic signal	Filter differential pressure trend showed periodic spikes correlating precisely with trip events, and fuel samples taken during those periods showed water content far above spec
Prevention	Periodic water-in-fuel sampling schedule; drain valve function test added to the PM program

2. Symptom

- **Intermittent low fuel pressure trips** occurred during routine generator testing and operation — not on every test, and not correlated with an obvious pattern initially.

3. Why This Wasn't Assumed to Be a Fuel Pump Problem

Low fuel pressure trips point most directly at the fuel transfer/injection pump itself — a worn pump, an air leak in the suction line, or a pump control issue. But the **intermittent** nature of

the trips (not every test, no clear mechanical pattern) suggested something **episodic** was happening on the supply side, rather than a continuously degraded pump that would be expected to trip more consistently.

4. Diagnostic Approach

Step 1 — Review trip events for a pattern

Trip event timestamps were reviewed for any correlation with test conditions, load, or time of day — no clear pattern emerged initially, reinforcing that the cause was likely episodic rather than load- or wear-related.

Step 2 — Review fuel filter differential pressure trend

Filter/coalescer differential pressure was trended at higher resolution around each trip event, rather than just checked as an instantaneous reading.

Finding: Differential pressure showed **periodic spikes**, and these spikes **correlated precisely with the timing of trip events**.

Step 3 — Sample fuel quality during an affected period

A fuel sample was taken during a period immediately following a trip/dP spike event and sent for **Karl Fischer water content analysis**.

Finding: Water content was **far above the fuel specification**, confirming a water contamination event rather than a purely mechanical filter fouling issue.

Step 4 — Trace the source of the intermittent water contamination

With water contamination confirmed as episodic (spiking, not a constant elevated baseline), the day tank's **water drain system** — designed to automatically remove any water that settles to the tank bottom — was inspected.

Finding: The **water drain float valve had failed**, allowing water to accumulate in the tank rather than being continuously removed, and then periodically **slug into the fuel draw** when tank agitation (e.g., from fuel transfer pump cycling or a test start) disturbed the settled water layer.

Quantitative Basis

- Fuel water content spec: ≤ 500 ppm. Baseline samples: **180-220 ppm**. Samples taken during trip-correlated periods: **2,400-3,100 ppm** — 5-6x the spec.
- Filter/coalescer differential pressure: normal operating range 3-6 psi. Spikes during trip events reached **22-28 psi**, briefly exceeding the filter's rated bypass/trip threshold.
- Water drained from the day tank bottom (once the float valve was inspected and manually drained) measured **14 gallons** — a substantial accumulation for a system designed to auto-drain continuously.

5. Root Cause

The day tank's water drain float valve had failed, allowing water (from condensation and minor fuel delivery contamination over time) to accumulate at the tank bottom instead of being continuously removed. Tank agitation during fuel transfer or generator start periodically disturbed this settled water layer, sending a **slug of water** into the fuel filter/coalescer that

exceeded its water separation capacity, allowing water-contaminated fuel to reach the engine and trigger low fuel pressure trips.

6. Corrective Action

1. **Repaired/replaced the water drain float valve.**
2. **Manually drained the accumulated water** from the day tank.
3. **Replaced the fouled filter/coalescer elements.**

7. Verification

- Fuel water content, sampled over the following **10 test cycles**, held in the **170-210 ppm range**, within the 500 ppm spec throughout, with no spike events.
- Filter differential pressure held in the normal **3-5 psi range** across the same test cycles.
- **Zero low fuel pressure trips** over the following **90 days**, spanning routine monthly testing and one actual emergency-start event.

8. Prevention / Long-Term Fix

- Established a **periodic water-in-fuel sampling schedule**, independent of trip events, so accumulation is caught proactively.
 - Added a **drain valve function test to the preventive maintenance program**, since a failed float valve otherwise gives no indication of failure until water has already accumulated to a problematic level.
-

9. General Troubleshooting Checklist (Reusable)

- ☐ Review trip event timing for a pattern (load-correlated favors a mechanical/wear cause; episodic/no pattern favors an intermittent contamination or supply-side cause)
- ☐ Trend fuel filter/coalescer differential pressure at high resolution around trip events, not just as an instantaneous check
- ☐ If dP spikes correlate with trip timing, sample fuel quality (water content via Karl Fischer) during an affected period
- ☐ If water contamination is confirmed and episodic (not a constant elevated baseline), inspect the day tank's water drain system for a failure allowing accumulation
- ☐ Repair the drain mechanism and remove accumulated water directly, not just replace fouled filters
- ☐ Confirm recovery via BOTH fuel water content trending AND filter dP trending across multiple subsequent test cycles
- ☐ Add periodic water-in-fuel sampling and drain valve function testing to the standing PM program for emergency/standby fuel systems, since these systems don't get the continuous operational scrutiny of primary equipment

10. Key Takeaway

Intermittent, seemingly random trips on emergency/standby equipment are often a sign of an **episodic** contamination event rather than continuous wear — and fuel systems on standby generators are particularly prone to slow water accumulation, since they don't get the frequent turnover and inspection that primary fuel systems do. A failed automatic drain valve can quietly accumulate water for months with zero indication until a disturbance sends a slug of it into the filter — trend filter dP

at high resolution around trip events, and check the drain system directly rather than assuming a fuel pump fault.

Related Concepts / Tags

diesel-generator emergency-power fuel-contamination water-in-fuel fuel-coalescer day-tank drain-valve Karl-Fischer standby-equipment

This guide is derived from a representative field troubleshooting scenario. Values and thresholds shown are illustrative and should be validated against your own unit's design basis before applying.