

FIELD SERVICE REPORT

SERVICE REPORT NO. SMPL-FSR-0001	DATE 15-09-2026	CASE ID CS-2026-0915-0042	CALL TYPE Warranty	CALL STATUS ✓ Complete
-------------------------------------	--------------------	------------------------------	-----------------------	---------------------------

CUSTOMER		PRODUCT & CALL	
NAME	7Minion Technology Pvt. Ltd.	MODEL	APC Smart-UPS SRT10KXLI
ADDRESS	WDWFEFWGRG, Tower B, 9th Floor, Sector 62, Gurugram, Haryana - 122011	UPS SR NO.	210924H95V
PHONE • EMAIL	+91-98765-43210 • accounts@7minion.com	CALL TYPE	Warranty
GSTIN	06AAACZ8266C1Z9	OEM CALL	Yes

PROBLEM REPORTED	UPS beeping in battery mode with intermittent output voltage fluctuation during office hours
------------------	--

REASON FOR VISIT	Warranty — Check battery bank health and mains input wiring
------------------	---

VISIT TIMING		SITE OBSERVATION	
ARRIVAL	15/09/2026 15:10	MAINS L-N	228 V
DEPARTURE	15/09/2026 16:50	MAINS N-E	4 V
ON-SITE TIME	1h 40m	AC PROVIDED	Yes
PREFERRED VISIT	14/09/2026 22:00	DG PROVIDED	No
		ENV. DUTY	Yes
		UPS LOCATION	Server Room — 2nd Floor

CONNECTED LOAD		POWER CONDITION	
PC	21" × 4 19" × 2	DG SET	No
PRINTER	300W × 1	DG CAP. (KVA)	—
SCANNER	200W × 1	AMF PANEL	Yes
POWER FAILURES	6 nos / 45 min	NON-BIZ / HOL.	Yes / No
LOAD ON DG	0 %		

BATTERY RECORD							
MAKE Exide		VOLTAGE 12V		AH 100Ah		QTY 16	
CHARGING VOLTAGE							
B1	B2	B3	B4	B5	B6	B7	B8
13.8	13.7	13.8	13.6	13.7	13.8	13.7	13.6
B9	B10	B11	B12	B13	B14	B15	B16
13.8	13.7	13.5	13.8	13.7	13.6	13.8	13.7
DISCHARGING VOLTAGE							
B1	B2	B3	B4	B5	B6	B7	B8
12.9	12.8	12.9	12.7	12.8	12.9	12.8	12.7
B9	B10	B11	B12	B13	B14	B15	B16
12.9	12.8	12.6	12.9	12.8	12.7	12.9	12.8

PART REPLACEMENT					
#	Item Replaced	Old Sr No	New Sr No	Qty	Charges ₹
1	Battery 12V 100Ah	EXD22A001	EXD26I101	2	₹ 12,500
2	DC Capacitor 4700uF	CAP-8812	CAP-9031	1	₹ 1,800
3	Cooling Fan 120mm	FAN-4410	FAN-5523	2	₹ 950
4	Control Card	CTL-1102	CTL-1187	1	₹ 6,400
5	Fuse Kit 63A	FUS-0063	FUS-0071	4	₹ 450

FEEDBACK & SIGN-OFF	
FSE FEEDBACK	Battery bank healthy; two cells (B11 charging, B11 discharging) read marginally low — advised replacement within 90 days. Mains wiring tightened at the input MCB and load wiring verified.
CUSTOMER FDBK	Engineer explained the battery readings and the AMC renewal options. Site left clean; UPS running normally on mains at departure. Satisfied with the visit.
RATING	9 / 10
FSR STATUS	☒ Complete ☐ Under Obs. ☐ Incomplete
FSR VERDICT	—

CUSTOMER		FIELD SERVICE ENGINEER	
Signature	Name: Rahul Sharma	FSE Signature	Name: Amit Kumar No: +91-98111-22334
Office Seal	Date		Date