Tukang Copilot

Repair Report

#b6e6d30d1e40

CAUTION Safety

Caution for hot engine parts and flammable petrol vapour around spark area. No high-voltage mains work, but keep ignition OFF until ready to test and avoid fuel contact.

Item

Honda Beat scooter engine cylinder head and spark plug area

Problem

Honda Beat cranks but does not fire. Photo shows spark plug cap completely off the spark plug, so engine is getting no spark.

Cause worked on

Disconnected spark plug cap - no spark reaching plug

Photo with the parts marked (SAM 3.1)



Likely causes

88% Disconnected spark plug cap - no spark reaching plug

55% Fouled or worn spark plug

35% Aged ignition wiring / plug cap connection fault

Before you start, make sure

- ☐ Engine OFF, key OFF, and engine fully cool to touch
- ☐ Bike on center stand in open air away from open flame
- ☐ Hands dry, no strong petrol smell or active fuel leak

Steps (0/5 verified by camera)

1. Turn ignition key to OFF and remove it. Put bike on center stand outdoors and let engine cool until cold to touch.
   -> ignition key removed, bike upright on center stand with engine cold
2. Wipe dust and dirt around cylinder head and spark plug with a dry cloth. Do not pull any wires.
   -> cylinder head area around spark plug is wiped clean and clearly visible
3. Look at the rubber spark plug cap and spark plug top. Check the cap is not cracked and the tip is clean.
   -> spark plug cap held near spark plug, rubber intact without cracks
4. Push the spark plug cap straight down firmly onto the spark plug until you feel a click. Tug lightly to confirm it stays.
   -> the plug cap is pushed fully onto the spark plug, no gap
5. Turn key ON and start the engine normally with the starter. Listen for steady idle.
   -> spark plug cap remains firmly on spark plug with engine started

Engine starts and idles steadily with plug cap firmly attached and no repeated stalling.

Tools

- Spark plug wrench 16mm	**Rp35.000**
- Dry cloth and small cleaning brush	**Rp15.000**

Parts

- Spark plug NGK CPR7EA-9 for Honda Beat	**Rp25.000**
- Spark plug cap for Honda Beat	**Rp40.000**

Estimated parts cost: Rp65.000 ~20 min

Typical shop price (labour + parts): Rp100.000

Saved by doing it yourself (parts only): Rp35.000

What the AI did

- 0s Scanned your words for hazards (gas, mains, brakes...): clear [code]
- 14s Looked at the photo: Honda Beat scooter engine cylinder head and spark plug area, 5 parts located [muse-spark-1.3] 13.7s
- 21s Outlined 5 of 5 parts on your photo (pixel masks) [sam-3.1] 7.2s
- 35s Most likely: Disconnected spark plug cap - no spark reaching plug (88%), out of 3 causes [muse-spark-1.3] 13.8s
- 49s Planned 5 steps for: Disconnected spark plug cap - no spark reaching plug [muse-spark-1.3] 14.7s
- 49s Plan checked by safety rules in code: passed (CAUTION) [code]

Under the hood: models used

- Text safety gate: rules in code
- Look at photo: muse-spark-1.3 13.7s
- Mark parts: sam-3.1 7.2s
- Diagnose: muse-spark-1.3 13.8s
- Plan steps: muse-spark-1.3 14.7s
- Plan safety gate: rules in code

Light repairs only. Prices are estimates. For gas, house wiring, or high voltage, call a professional.

Tukang Copilot
Mechanic brief

Print this page or show it to the workshop so they don't start from zero.

Status

The owner is still on it, no result yet

What was found

Honda Beat scooter engine cylinder head and spark plug area
Honda Beat cranks but does not fire. Photo shows spark plug cap completely off the spark plug, so engine is getting no spark.
Seen in the photo: spark plug cap is detached from spark plug and hanging above it; heavy dust and dirt coating on engine, frame and hoses; dark oily residue below cylinder head joint; text seen in photo: "Sample photo (AI-generated)" at top left
- Disconnected spark plug cap - no spark reaching plug (88%): spark plug cap is detached from spark plug and hanging above it in photo; owner says starter turns but engine doesn't fire, classic no-spark symptom
- Fouled or worn spark plug (55%): spark plug ceramic and metal look dirty in report; heavy dust and dirt coating on engine
- Aged ignition wiring / plug cap connection fault (35%): wiring connector wrapped in aged black electrical tape; dusty ignition cables and taped area near cylinder head
Parts marked: 1. spark plug, 2. spark plug cap, 3. cylinder head, 4. engine fan cover, 5. wiring connector

What was tried

- Being tried now: Disconnected spark plug cap - no spark reaching plug

Owner's photos



Photo 1