

MEDSUPPLY EUROPE GMBH

Pharmaceutical Distribution and Logistics
Kaiserstrasse 45, 60311 Frankfurt am Main, Germany
Tel: +49 69 1234 5678 | quality@medsupply-europe.de

FORMAL QUALITY COMPLAINT - PACKAGING DEFECT

Reference: MSE-QC-2024-0315 | Priority: HIGH

1. PRODUCT IDENTIFICATION

Product Name:	Amoxicillin Trihydrate Capsules
Strength / Grade:	500 mg / USP Grade
Batch / Lot Number:	BX-20240315-002
Manufacturing Date:	15 January 2024
Expiry Date:	14 January 2026
Total Quantity Received:	1,000 units (100 HDPE bottles)
Quantity Affected:	50 units (50 bottles with defective induction seals)
Purchase Order No.:	PO-DE-2024-0891

2. COMPLAINT SOURCE AND DATE

Source of Complaint:	Email
Date Complaint Raised:	15 March 2024
Date Product Received:	12 March 2024
Receiving Warehouse:	Frankfurt Distribution Centre, Germany
Reported By:	Hans Weber, QA Manager, MedSupply Europe GmbH

3. DESCRIPTION OF PACKAGING DEFECT

During routine incoming goods inspection at our Frankfurt warehouse on 12 March 2024, our QC team identified that 50 of the 1,000 HDPE bottles received had broken or improperly formed induction seals.

Specific observations:

- 47 bottles: foil induction seal liner not bonded to bottle neck at all
- 3 bottles: seal partially bonded but removable without resistance
- All affected bottles: outer cap properly applied, no tampering signs
- Capsule contents: inspected and appeared physically intact

All 50 affected bottles have been quarantined (Location: QRJ-FRA-047). The remaining 950 bottles are on quality hold pending investigation.

4. ROOT CAUSE ASSESSMENT (INITIAL)

The defect is consistent with a sealing equipment issue or temperature deviation during the induction sealing process.

Likely causes include:

- Insufficient sealing head temperature during packaging run

- Incorrect dwell time during sealing operation
- Foil liner material batch inconsistency
- Equipment calibration drift between last qualification and this batch

5. IMPACT ASSESSMENT

Complaint Type:	Packaging Defect
Severity:	MAJOR
Priority:	HIGH
Patient Safety Risk:	Product integrity compromised - contamination risk if distributed
Regulatory Obligation:	Potential BfArM notification if released-to-market units identified

6. REQUESTED RESPONSE TIMELINE

IMMEDIATE (within 24 hours):

- Written acknowledgement of this complaint
- Confirmation of batch hold status at manufacturing site

SHORT-TERM (within 5 working days):

- Preliminary investigation report
- Guidance on disposition of 950 quarantined units
- Replacement shipment arrangement

MEDIUM-TERM (within 15 working days):

- Full root cause analysis report
- CAPA plan with implementation dates
- Preventive measures for future batches

Filed under Quality Agreement Ref: QA-2023-MSE-042. Hans Weber, QA Manager - MedSupply Europe GmbH - 15 March 2024