

한국전력공사 TiFRONT-BS9710 펌웨어 업데이트 가이드

2021.08 파이오링크 TiFRONT사업실



CONTENTS

Ⅱ 펌웨어 업로드

- 가 Master MSU에 펌웨어 업로드
- 나 BACKUP MSU에 펌웨어 동기화
- 다 라인카드에 펌웨어 업로드

Ⅲ 펌웨어 적용

- 가 **장비 재부팅**
- 나 **컨피크 수정**



펌웨어 업로드



- 설치가이드는 console 작업을 기준으로 작성 되었습니다. 업데이트 전 running-config 를 백업 받으시기 바랍니다.
- 1. MGMT IP 세팅
 - 펌웨어를 업로드 하기 위한 IP를 세팅합니다. 본 가이드는 MGMT 포트를 이용해 노트북에서 장비로 펌웨어를 업로드 하는 방법을 설명합니다.
 - Show ip interface brief 명령어로 인터페이스 확인(MGMT포트는 gigaethernet5/0 or 6/0 임)

Switch#show ip int	erface brief		
Interface	IP-Address	Method Prot	ocol-Status
GigaEthernet5/0	unassigned	manual down	1
Nul 10	unassigned	manual up	
VLAN1	192.168.192.151	manual up	
VLAN200	192,168,200,200	manual down	ı
Switch#			

• MGMT IP 세팅


Switch#conf Switch_config#interface gigaEthernet 5/0 Switch_config_g5/0#ip address 192.168.212.100 255.255.255.0 Switch_config_g5/0#

MGMT IP 세팅 확인

Switch#show ip interface	brief	
Interface	IP-Address	Method Protocol-Status
GigaEthernet5/0	192.168.212.100	manual down
NullO	unassigned	manual up
VLAN1	192.168.192.151	manual up
VLAN200	192.168.200.200	manual down
Switch#		



- 2. TFTP 서버 세팅
 - 노트북을 tftp 서버로 세팅
 - 3CDaemon 설정





- 3. MSU에 펌웨어 업로드
 - 노트북 IP대역을 MGMT IP 대역과 맞추고 mgmt 포트와 케이블로 연결한다.
 - Ping으로 장비와 노트북 간 연결을 확인한다.
 - Dir 명령어로 현재 업로드 된 펌웨어 확인
 - switch.bin : MSU 펌웨어
 - LS6020_BIN / LS5020_BIN : 라인카드 펌웨어

```
Switch#dir
Listing Directory /:
    switch.bin
                            <FILE>
                                              9127741
                                                           Jun 24 09:56:28 2021
    LS6020 BIN
                            <FILE>
                                              6072313
                                                           Jun 24 10:01:36 2021
    LS5020_BIN
                            <FILE>
                                              3746864
                                                           Jun 24 10:04:46 2021
                            <FILE>
                                                6577
                                                           Jan 01 11:43:36 1970
     startup-config
     SYS CORE DUMP
                           <FILE>
                                              786432
                                                           Jan 01 00:01:04 1970
free space is 47214592 bytes
Switch#
```



- 3. MSU에 펌웨어 업로드
 - MSU 펌웨어 업로드

```
Switch#copy tftp: flash:
Source file name[]?BD_MSU6020_4.1.2B_78700.bin
Remote-server ip address[]?192.168.212.130
Destination file name[BD_MSU6020_4.1.2B_78700.bin]?switch.bin
```

• 설명(**저장할 파일명은 대소문자 구별하여 정확이 입력해야 정상적으로 적용됨**)

Source file name[]? 노트북에 저장되어 있는 펌웨어 파일명 Remote-server ip address[]? TFTP 서버(노트북) IP Destination file name[BD_MSU6020_4.1.2B_78700.bin]?저장할 파일명(switch.bin / LS5020_BIN / LS6020_BIN)

• 업로드 확인: show logging으로 업로드 성공 확인

```
Switch#show logging
Syslog logging: enabled (0 messages dropped, 0 flushes, 0 overruns)
Console logging: level debugging, 184 messages logged
Monitor logging: level debugging, 0 messages logged
Buffer logging: level debugging, 184 messages logged
Trap logging: level informational, 0 message lines logged

Log Buffer (4000000 bytes total 3985815 bytes remain):
Jan 1 12:13:09 TFTP:successfully receive 17470 blocks, 8944542 bytes
Jan 1 12:13:08 file flash:switch.bin, successfully wrote
```



- 3. MSU에 펌웨어 업로드
 - LS6020 라인카드 펌웨어 업로드

```
Switch#copy tftp: flash:
Source file name[]?BD_LS6020_4.1.2B_78700.bin
Remote-server ip address[]?192.168.212.130
Destination file name[BD_LS6020_4.1.2B_78700.bin]?LS6020_BIN
```

업로드 확인 : show logging으로 업로드 성공 로그 확인

```
Jan 1 12:36:51 TFTP:successfully receive 11788 blocks, 6035185 bytes Jan 1 12:36:49 file flash:LS6020_BIN, successfully wrote
```

• LS5020 라인카드 펌웨어 업로드

```
Switch#copy tftp: flash:
Source file name[]?BD_LS5020_4.1.2B_78700.bin
Remote-server ip address[]?192.168.212.130
Destination file name[BD_LS5020_4.1.2B_78700.bin]?LS5020_BIN
```

업로드 확인: show logging으로 업로드 성공 로그 확인

Jan 1 12:48:00 TFTP:successfully receive 7251 blocks, 3712362 bytes Jan 1 12:47:58 file flash:LS5020_BIN, successfully wrote



I - 나. BACKUP MSU에 펌웨어 동기화

- 3. BACKUP MSU에 펌웨어 동기화
 - MSU 펌웨어 동기화

```
Switch#update msu switch.bin
start update peer msu file, please wait.....
Jan 1 13:57:08 check SLOT 6 10S consistency......
Jan 1 13:57:08 SLOT 6 is forced to update, start updating......
Switch#
```

MSU 펌웨어 업로드 성공 확인 (5 분정도 소요)

```
Jan 1 14:02:23 SLOT 6 update session ends, consumed time is 315s

Jan 1 14:02:23 successful send flash:/switch.bin to SLOT 6,file flush finished

Jan 1 13:57:08 SLOT 6 is forced to update, start updating......
```



I - 나. BACKUP MSU에 펌웨어 동기화

- 3. BACKUP MSU에 펌웨어 동기화
 - 라인카드 펌웨어 동기화 및 확인 (각각 5분정도 소요)

```
Switch#update msu LS5020_Bln
start update peer msu file, please wait.....
Switch#
```

```
Switch#update msu LS6020_BIN start update peer msu file, please wait.....
```

라인카드 펌웨어 동기화 확인

```
Jan 1 14:06:07 successful send flash:/LS5020_BIN to SLOT 6,file flush finished
Jan 1 14:03:45 SLOT 6 is forced to update, start updating.....
```

```
Jan 1 14:09:51 successful send flash:/LS6020_BIN to SLOT 6,file flush finished

Jan 1 14:06:09 SLOT 6 is forced to update, start updating......
```



I-다. 라인카드에 펌웨어 업로드

- 1. MSU에 업로드 된 펌웨어를 각 라인카드에 업로드 시킴
 - 라인카드로 업로드

```
Switch#update Is update all slot forcely start update Is file, please wait.....
Switch#
```

각 라인카드 별로 업로드 완료 로그 확인 (각 라인카드 별 5~10분 소요)

```
Jan 1 13:35:41 SLOT 2 update session ends, consumed time is 203s
```

Jan 1 13:35:41 successful send flash:/LS5020_BIN to SLOT 2,file flush finished



펌웨어 적용



ш- 가. 장비 재부팅

- 1. 업로드 된 펌웨어를 적용 시키기 위해서는 장비를 재부팅 시켜야 함
 - 반드시 redundancy reload shelf 명령어로 재부팅 시켜야 펌웨어가 정상 적용 됨

cf) reboot 명령어로 재부팅 시 Master MSU 만 재부팅 됨

```
Switch#redundancy reload ?

peer — Reloads the redundant peer CPU switch module
shelf — Reloads both redundant CPU switch modules in the shelf
Switch#redundancy reload shelf
```

- Redundancy reload shelf 명령어로 재부팅 시 Master MSU가 바뀌므로 console을 Master MSU에 연결시켜 준다.
- 재부팅 후 show version으로 펌웨어 정상 적용 확인

```
Switch#show version
PIOLINK Inc. Internetwork Operating System Software
BS97-MSU-VI Series Software, Version 4.1.2B Build 78700 RELEASE SOFTWARE
Copyright(C) PIOLINK Inc. All rights reserved
Compiled: 2020-11-23 15:41:8 by SYS, Image text-base: 0x108000
ROM: System Bootstrap, Version 0.5.2.hardware version:2
Serial num:SM73000439, ID num:SM73000439
System image file is "flash:/switch.bin"
PIOLINK BS97-MSU-VI RISC
524288K bytes of memory,65536K bytes of flash
Base ethernet MAC Address: fc:fa:f7:44:6f:b0
BOARD num:11000277 PCB version:2
CPLD version: A BOARD type: VI
snmp info:
 product_ID:124 system_ID:1.3.6.1.4.1.3320.1.124.0
Switch uptime is 0:00:04:40, The current time: 1970-1-1 0:5:13
 Reboot history information:
 No. 1: System is rebooted by backplane
 No. 2: System is rebooted by software at 1970-1-1 14:12:52, flag:000d0009, uptime
 No. 3: System is rebooted by backplane
Switch#
```



Ⅲ- 나. 컨피그 수정

- 1. 기존 펌웨어와 업데이트 펌웨어 간 암호 저장 방식의 차이가 있어 계정을 다시 생성해 주어야함.
 - Username [계정] password 2
 - Enable level 15 password 2

```
Switch_config#username piolink password 2
Please input password:
Please input the password AGAIN:
Switch_config#
```

```
Switch_config#enable level 15 password 2
Please input password:
Please input the password AGAIN:
Switch_config#
```

• Show running-config 로 계정 생성 확인

```
username admin password 6 $5$23502334e626b42346676b891b1e40f58f51f45c3e0faad77c7 940ea386323102a5635c2 username Switch username piolink password 6 $5$175808767e1daaddae63d760c903faeeba7c7a5ca87bbe795 5d7c4edd76024bb5186efac ! enable password 6 $5$98329553a288796f195781cc5fe5cbc174a8e1e86c2190d7eeb3a812501 d77bcafb958b7 level 15
```



Ⅲ- 나. 컨피그 수정

- 2. 업데이트 전 Telnet을 활성화 하여 사용하고 있었다면 업데이트 후 Telnet을 활성화 해야한다.
 - Ip telnet enable

```
ip telnet attack-defense
ip telnet enable
```

3. 모든 설정을 마쳤다면 write 명령어로 설정을 저장한다.

```
Switch#write
Saving current configuration...
OK!

Synchronizing startup-config to backup card...
OK!
Switch#Jan 1 16:29:19 TID:5f88280, writing file flash:/startup-config
Jan 1 16:29:26 file flash:/startup-config, successfully wrote
Jan 1 16:29:27 check SLOT 5 IOS consistency......
Jan 1 16:29:28 SLOT 5 is forced to update, start updating......
Switch#
```