

10456 170 STREET, EDMONTON, AB T5S 1M4 TEL: (780) 444-0829 FAX: (780) 444-0854 Toll free : 1-877-736-7287 www.ctrca.com

Customer ID: CG-LOB001

LOBLAWS INC.

ATTN: MIRO PROCESSING 101 WESTON STREET WINNIPEG, MB R3E 2T4 Telephone: 1-855-337-2367 INVOICE

Invoice No.: 25815

Invoice Date: 6/10/2019 GST # 86652 1834 RT

CONTRACT#

WORK ORDER # 34268

PO NUMBER: 4200377009

Service location:

SHOPPERS DRUG MART #2341

10015 107 STREET

WESTLOCK, AB T7P2K7

**Description:** ALARMS

## Work Report

12-24-18

Drove to site. Checked coils and fans. Went to roof. Checked condensing unit. Unit running low suction pressure, sight glass flashing. Put refrigerant until sight glass was cleared. Pumped down system and checked TXV screens. Txv screens were plugged, they were cleaned with nitrogen. Checked system operation. Unit working okay. Fan making noise. Fan blade was loose. Tightened fan blade screw. Checked thermostat settings. Leak Checked. Cleaned up.Checked walk in cooler. Checked thermostat settings

Unit working okay

Quantity	Description	Unit Price	Amount
6.50	Overtime	139.88	909.19
182.00	MILEAGE CHARGE	0.75	136.50
1.00	SUNDRY	15.00	15.00
1.00	LEAK CHARGE	35.00	35.00
1.00	EVACUATION CHARGE	35.00	35.00
5.00	R404A REFRIGERANT & ENVIRONMENTAL LEVY	20.80	104.00
	6.50 182.00 1.00 1.00 1.00	6.50 Overtime 182.00 MILEAGE CHARGE 1.00 SUNDRY 1.00 LEAK CHARGE 1.00 EVACUATION CHARGE	6.50 Overtime 139.88 182.00 MILEAGE CHARGE 0.75 1.00 SUNDRY 15.00 1.00 LEAK CHARGE 35.00 1.00 EVACUATION CHARGE 35.00

Material	104.00
Labour	909.19
Other	221.50

Total Amount Due:	\$1,296.43
GST	61.74
Billable Subtotal:	1,234.69



#### SERVICE REPORT

WORK ORDER:

34268

DATE: 12/24/2018

CUSTOMER: SHOPPERS DRUG MART #2341 (AR#:CG-

LOB001)

SITE ALIAS: SDM 2341

STREET: 10015 107 STREET
CITY: WESTLOCK, AB T7P2K7

CONTACT: Issaka

MAKE: KEEPRITE (ID# 6378)

MODEL: KEZA050M6-HT3B-N171

SERIAL #: 102303652 INSTALLED AT: Drink cooler

DESCRIPTION: Cooler

CALL TYPE: Refrigeration - Service

TROUBLE REPORTED: Alarms

WORK PERFORMED: Drove to site

Checked coils and fans

Went to roof

Checked condensing unit

Unit running low suction pressure, sight glass flashing

Put refrigerant until sight glass was cleared Pumped down system and checked TXV screens

Txv screens were plugged, they were cleaned with nitrogen

Checked system operation

Unit working okay
Fan making noise
Fan blade was loose
Tightened fan blade screw
Checked thermostat settings

Cleaned up (TANGARIFE NUNEZ; JAIME on Dec 24, 2018)
Leaked checked (TANGARIFE NUNEZ; JAIME on Dec 24, 2018)

Checked walk in cooler Checked thermostat settings

Unit working okay (TANGARIFE NUNEZ; JAIME on Dec 24, 2018)

PARTS			
QUANTITY	DESCRIPTION		
5	REFRIGERANT & ENVIRONMENTAL LEVY		
1	TRUCK CHARGE		
1	SUNDRY		

REFRIGERANT				
CHANGE	REFRIGERANT	QTY (PDS)		
Add	R404A - REFRIGERANT & ENVIRONMENTAL LEVY	5		

LABOR		
DATE	LABOR	TECHNICIAN/DESC
12/24/2018	6.5 (Overtime)	TANGARIFE NUNEZ;JAIME (General)

### IS JOB COMPLETE? Yes

Customer

Name: Shana

Date: 12/24/2018 01:08 AM

Comments:

## Technician

Name: JAIME TANGARIFE NUNEZ Date: 12/24/2018 01:08 AM

Comments:

**Email** 

# **Customer Signature**

Technician Signature

## LOBLAWS INC. REFRIGERANT LEAK REPORT

	- 60		STOR	E SERVICED AND	WORK ORDER INF	ORMATION	
[Store Name] [Street Address](0015 107 57 [City, Province, Postal Code]   Westlook   AD				В	Loblaw Maintenance Help Desk Work Order Number: Contractor Work Order Number: Invoice Number: Fan Desk Work Order Number: 3 4 2 6 Invoice Date:		
			10.55 - 1 - 1	SERVIC	CE CONTACTOR		
[Contractor Name] [Street Address] [City, Province, Postal Code] ODP/ODS No.:					Service Technician Name(s):  Jaime Tangarile Nunez		
				UNIT/SYST	EM INFORMATION		
System Affected: Refrigeration  HVAC Other  Source of leak: Manufactured equipment  Equipment new install Piping				II Piping	Manufacturer: Keeprite Unit Model Number: KE2AO50M6-HT3B-N171 System Identification: 102303652 Amount of Refrigerant in System (Ibs): 20C5 (estimated.) Refrigerant Type (use ASHRAE #): 404A		
			JIII 0, 17,53	LEAK	DESCRIPTION		
Leak Cause:	Leak Cause:  Compressor Service Cop losse Suction Service Valve Cap looke.						
Leak Discov	ery (How	was it four	id?): /-em	K Check	. ~		
		SHOW INDIVI	DUAL REPAIRS		INFORMATION A NEW FORM IF MO	RE THAN 2 REPAIRS FOR ON	E LEAK)
Service Dat	te Amo	ount Amoded Adde		pair Description (p	lease be specific).	Include repair performed th repair was performed.	
12/24/201	19 5			ightened.	Service Can Ye		4.25.
	ling to rep systems i	oort a refrigera is (amount lea	refrigerant lea ant leak on beh aked) kilograms	k by phone to the P alf of Loblaws Inc. fo My name is (name	or the site located at ( e of technician) and I	ody, please use the following (store banner and address). T am working for (name of serv	he amount added into the ice company).")
Date MM/DD/ YYYY	Amount Added (kg)	Leak Exceeds Provincial Threshold (Y/N)	Provincial Regulatory Body Notified (Y/N)	Date and Time Report (MM/DD/YYY HH:MM)	Reporting	Confirmation Number (N/A if fax or email)	Name of Officer/Agent who took call (phone report), Fax Number (fax report) or Email Address (email report)
12/24/19	2.	ho	No			<u> </u>	
Contactor S Date	ignature				information provide and that all refriger	his report to Loblaws Inc., Cor ed in this report is accurate to rant replenishment requests a oved by Loblaws Inc. prior to	the best of their knowledge, nd/or invoicing shall be

Report must be sent electronically to <a href="https://linear.com/