



SERVICE REPORT

REHOTEQ Technologies
Okitipupa, Ondo State

RF-2026-00184
08 Oct 2026
Draft

Customer	Mr. Adewale Ade
Phone	0803 000 0000
Location	14 Adeyemi St, Okitipupa
Service	Inverter fault diagnosis
Trade	SOLAR
Equipment	6.2 kVA · SMS-II 6.2K
Serial no.	SMS62-2024-88314
Installed	2025-07-24

FAULT REPORTED

Low battery warning; E03 on load. Inverter shuts down when the fridge starts.

DIAGNOSIS

Loose DC terminal on battery 3. Bank drops to 44.1 V under load, triggering overcurrent protection.

WORK PERFORMED

Re-terminated DC lugs, torqued to 12 Nm, rebalanced bank, ran a 15-minute load test at 2.1 kW.

MATERIALS & LABOUR

35 mm² copper lug (2)	NGN 3,000
Heat-shrink kit (1)	NGN 1,500
Labour	NGN 25,000

TOTAL	NGN 29,500
-------	------------

RECOMMENDATION

Battery bank at 71% state of health. Budget for replacement within 6 months.

CHECKLIST - INVERTER FAULT DIAGNOSIS (2/3)

- [x] Isolate AC supply and lock off before opening
- [x] Measure open-circuit battery voltage at inverter terminals
- [] Customer handover and sign-off

PHOTOGRAPHIC EVIDENCE

BEFORE - inverter bay 08 Oct 2026 09:14 6.4975N 4.7814E Toye A.	BEFORE - inverter bay 08 Oct 2026 09:14 6.4975N 4.7814E Toye A.	BEFORE - inverter bay 08 Oct 2026 09:14 6.4975N 4.7814E Toye A.
BEFORE	DURING	AFTER

Captured 08 Oct 2026 · 09:14 · 6.4975° N, 4.7814° E · Toye Adewale

CUSTOMER



A. Adewale

08 Oct 2026 11:41

TECHNICIAN



T. Adewale

08 Oct 2026 11:42

VERIFIED EVIDENCE

This report is tamper-evident. Verify at
rehoteq.ng/v/RF202600184

SHA-256 e3b0c44298fc1c149afb4c8996fb924

This report records work performed as described by the technician above. It is not a certificate of regulatory compliance unless issued by a licensed contractor.