



SERVICE REPORT

REHOTEQ Technologies
12 Sapele Road, Benin City, Edo State · 0803 000 0000

RF-2026-00001
10 Oct 2026
Completed

Customer	Mr. Adewale Ade
Phone	0803 000 0000
Location	14 Adeyemi St, Okitipupa, Ondo State
Service	Inverter fault diagnosis
Trade	SOLAR
Equipment	6.2 kVA · SMS-II 6.2K
Serial no.	SMS62-2024-88314
Installed	2025-07-24

FAULT REPORTED

Low battery warning; E03 on load. Inverter shuts down when the fridge starts.

DIAGNOSIS

Loose DC terminal on battery 3. Bank drops to 44.1 V under load, triggering overcurrent protection.

WORK PERFORMED

Re-terminated DC lugs, torqued to 12 Nm, rebalanced bank, ran a 15-minute load test at 2.1 kW.

MATERIALS & LABOUR

35 mm ² copper lug (2)	₦3,000
Heat-shrink kit (1)	₦1,500
Labour	₦25,000

TOTAL	₦29,500
--------------	----------------

RECOMMENDATION

Battery bank at 71% state of health. Budget for replacement within 6 months.

CHECKLIST - INVERTER FAULT DIAGNOSIS (9/11)

- ☒ Isolate AC supply and lock off before opening
- ☒ Record inverter model, firmware and error log
- ☒ Measure open-circuit battery voltage at inverter terminals
- ☒ Measure voltage again under surge load
- ☒ Inspect and feel DC terminations for heat damage
- ☒ Torque-check all DC connections
- ☒ Check battery state of health / BMS readout
- ☒ Verify inverter surge rating vs actual starting current
- ☒ Earth bond continuity check
- ☐ Load test on site and confirm the fault code clears
- ☐ Customer handover and sign-off

CUSTOMER

Adewale Ade

10 Oct 2026 14:00

TECHNICIAN

Toye Adewale

10 Oct 2026 14:01

RECORD & REFERENCE

Signed by both parties on 10 Oct 2026.

field.rehoteq.com/v/RF202600001

Photo 1 of 1 · SHA-256 e3b0c44298fc1c14...

This report records work performed as described by the technician above. It is not a certificate of regulatory compliance unless issued by a licensed contractor.