

Wire Harness Routing & Inspection

Document No: WI-3390-B | Revision: D | Station: Final Assembly | Est. Cycle Time: 12 min

Required Tools

- Flush-cut wire snips
- Continuity tester
- Torque screwdriver, 0.5-5 in-lb range

Required Materials

- Wire harness assembly, P/N WH-8842
- Nylon cable ties, 4 inch (qty 10)
- Bulkhead connector J12

Procedure

Step 1: Verify harness part number

Confirm the part number and revision printed on the harness tag matches the traveler for this build (WH-8842). Do not proceed if the part number does not match.

Step 2: Route harness along channel

Route the harness along wiring channel C-7 per the routing diagram posted at this station, maintaining a minimum 1 inch clearance from any moving components.

CAUTION: Do not route the harness within 3 inches of hydraulic lines. Chafing against a hydraulic line is a known failure mode at this station.

Step 3: Secure harness with cable ties

Secure the harness to the channel with a nylon cable tie approximately every 4 inches along its length. Trim excess tie length flush with flush-cut snips.

Step 4: Connect and torque connector J12

Mate connector J12 to the bulkhead receptacle. Using the torque screwdriver, tighten the connector's coupling nut to the specification below.

Spec: Torque = 2.5 in-lb $\pm$ 0.3 in-lb (connector J12 coupling nut)

Step 5: Continuity check

Using the continuity tester, verify continuity on all pins of connector J12 per the pin-out chart at this station. Mark this step Pass or Fail.

Step 6: Final dress and tie-off inspection

Confirm no harness segment sags more than 0.5 inch between tie points, no tie is over-cinched (visibly deforming the harness jacket), and all trimmed tie ends are flush. Mark this step Pass or Fail.