

BAY COUNTIES DIESEL SERVICE INC.

Service Invoice 42918

Name	North Sky	Contact	Justin	Created	02/27/26	Year	2018
Address	16701 SE McGillvray Blvd Suite 200 Vancouver, Wa 98683	Address 2	5275 Central Ave. Fremont, Ca 94536	Time	3:10 PM	Make	Ford
Home	Michel 971-412-8469	EstMiles		Invoiced	03/25/26	Model	F-750
Work	510-862-9946	V.I.N. #	1FDXF7DC0JDF03401	Advisor	Kevin	Lic#	YARZ345
Fax	209-579-3495	Engine Dat		Division	TR	Fleet#	72616
				PO#	Equip-Justin	Body	
				Checked By		Miles In	75,082
				Page#	1 of 1	Miles Out	75,082

Job Description

Check and Advise Engine Light on

Confirmed engine light on. Scanned ECM and checked for active faults. Confirmed active fault for nox conversion efficiency below threshold. Checked previous repair and functionality on nox sensor module installed and checked for malfunctions. Found Okay. Checked nox sensor and found oil pushing in to exhaust side. Inspect engine and found C.A.C tube torn and pushing oil from tube cold side to cooler to throttle valve. Advised customer recommend replacing contaminated nox sensor and replace torn C.A.C tube.

Advised customer might have Turbocharger failure on way out, system is burning oil.

Line Total	591.50
2.5 Hours Labor	492.50
Parts	99.00
Sublets	0.00

Part Number	Description	QTY	Each	Total
Computer Diagnostic Fee			99.00	99.00

Replace Torn C.A.C Hose Cold Side Cooler to Throttle Valve

Confirmed complaint, removed clamps and remove and replace torn C.A.C tube and torqued clamps to spec. Started engine and checked for leaks. Okay

Line Total	587.84
1 Hours Labor	197.00
Parts	390.84
Sublets	0.00

Part Number	Description	QTY	Each	Total
FC4Z-6F073-D	Tube	1	390.84	390.84

Install new Nox Sensors as Required

Confirmed and verified fail nox sensor. Removed connections and replaced nox sensor, cleaned connections and performed stationary regen. Monitored nox parameters and checked for active faults. Okay. Test drove unit with scan tool connected to ECM and rechecked for active faults. Okay. Drove unit back to customer location and returned back to service.

Line Total	1192.98
1.5 Hours Labor	295.50
Parts	897.48
Sublets	0.00

Part Number	Description	QTY	Each	Total
FC4Z-9D378-C	NOX SENSOR	1	897.48	897.48

Date Service Due

05/07/2026 90 Day Inspection
05/07/2026 B-PMI

Bay Counties Diesel Service | 42370 Boyce Road, Fremont, CA 94538

Telephone 510-490-5665 | Fax 510-490-2572

All repairs performed by Bay Counties Diesel Service Inc. are warrantied for a period of 1 year. Warranty covers only work performed by Bay Counties Diesel Service, and does not cover any related parts or repairs. Bay Counties Diesel Service is not responsible for any external costs, including, but not limited to, towing, lodging, of loss of revenue or down time. Bay Counties Diesel Service owns the right to make all repairs under warranty internally. Any truck left over 15 days will be subject to a \$150.00 a day storage fee.

Invoice Total	
Labor	\$985.00
Parts	\$1,387.32
Sublets	\$0.00
Supplies	\$39.40
Subtotal	\$2,411.72
Tax	\$136.09
Total	\$2,547.81