GLOBAL WING FINANCE BV | AIRCRAFT LEASING

Global Wing Finance BV

MAINTENANCE RESERVE CLAIM

Engine PRSV — ESN ESN-771201

Reference: MRC-N23456-2025-01

Aircraft Type	MSN	Registration	Engines	Year
Airbus A320-200	**8841**	**N23456**	**CFM56-5B4/P**	**2017**

Role	Party	Jurisdiction
Claimant (Lessee)	Meridian Express Corp.	USA
Reserve Account Holder	Global Wing Finance BV	Ireland
MRO Facility	Lufthansa Technik AG	Hamburg, Germany

CLAIM SUBMISSION

Dated: 2023-06-01

Meridian Express Corp.

This document is strictly confidential and is intended solely for the named parties. Any reproduction, disclosure, or distribution without the prior written consent of Global Wing Finance BV is strictly prohibited.

1. CLAIM SUMMARY

Parameter	Detail
Claim Reference	MRC-N23456-2025-01
Aircraft	Airbus A320-200 / N23456 / MSN 8841
Engine	CFM56-5B4/P / ESN ESN-771201 (Position 1)
Event Type	Performance Restoration Shop Visit (PRSV)
MRO Facility	Lufthansa Technik AG, Hamburg — EASA 145.0001 / FAA OM3R164L
Induction Date	2025-01-08
Completion Date	2025-03-22
Aircraft back in service	2025-03-28
Claim Submission Date	2025-04-10
Total Claim Amount	USD 1,117,570
MR Account Balance (Performance sub-account)	USD 824,000
MR Account Balance (LLP sub-account)	USD 416,000
Net Lessee Shortfall	USD 0 (accounts cover full claim)

2. REASON FOR SHOP VISIT

The engine was inducted for a Performance Restoration shop visit following sustained EGT margin deterioration and a high-pressure compressor stall event on 2024-12-18. EGT margin had degraded to 12°C against a monitoring threshold of 20°C. An on-wing borescope conducted on 2024-12-22 revealed:

Ref	ATA	Finding	Severity
BSI-001	72-30	HPT Stage 1 blades: 4 blades with tip erosion >AMM limits (>0.15 in)	MANDATORY REPAIR
BSI-002	72-30	HPT Stage 2 blades: 2 blades with leading edge nicks within limits — monitor	MONITOR
BSI-003	72-40	LPT Stage 4 Nozzle: 3 segments with oxidation burns exceeding AMM limits	MANDATORY REPAIR
BSI-004	72-20	HPC stages 5–7: performance coating loss contributing to EGT deterioration	PRICED WORKSCOPE
BSI-005	72-10	Fan blades: all within AMM limits; no damage	SERVICEABLE
BSI-006	72-50	No.1 and No.2 bearing compartment seals within limits	SERVICEABLE

3. AGREED WORKSCOPE

Task	ATA	Work Description	Qty	Status
WS-01	72-00	Complete engine disassembly; module split into 5 modules	N/A	Done
WS-02	72-10	Fan module: clean, inspect; restore tip clearances; replace 4 damaged fan blades	4 blades	Done
WS-03	72-20	LPC booster: disassembly; clean; inspect; replace full blade set Stage 2	Full set Stg 2	Done
WS-04	72-20	HPC: disassembly; SWET process on discs; replace HVOF coating Stages 5–7	Coating renewed	Done
WS-05	72-20	HPC Disc Stage 3: replace (CSN at 14,990 — within 10 of limit per LLP sheet)	1 disc	Done
WS-06	72-30	Combustion case: clean; inspect; 2 segments repaired per SRM 72-41-00	2 repairs	Done
WS-07	72-30	HPT Stage 1 blades: full replacement set — all new, RFN traceable	Full set (80)	Done
WS-08	72-30	HPT Stage 2 blades: replace 2 blades exceeding AMM limits	2 blades	Done
WS-09	72-30	HPT Stage 1 Nozzle Guide Vanes: full ring replacement	Full ring	Done
WS-10	72-30	HPT Stage 2 Nozzle Guide Vanes: full ring replacement	Full ring	Done
WS-11	72-40	LPT Stage 4 Nozzle: 6 segments repaired per SRM; remaining 3 replaced	3 segments	Done
WS-12	72-40	LPT blades Stages 4–7: clean, inspect; replace 8 blades (FOD/erosion)	8 blades	Done
WS-13	72-50	No. 1 Bearing: replace oil seals and	Seals replaced	Done

		carbon seals; bearing inspected (no replacement)		
WS-14	72-50	No. 3 Bearing: replace (at CSN limit per LLP sheet)	1 bearing	Done
WS-15	73-00	Fuel nozzles: replace all 20 (atomisation degraded)	20 nozzles	Done
WS-16	74-00	Igniter plugs: replace both (hours on limit)	2 plugs	Done
WS-17	72-00	Module reassembly; cold and hot section balance	N/A	Done
WS-18	72-00	Performance test cell — 3 runs; EGT margin confirmed at 62°C — PASS	N/A	PASS
WS-19	72-00	EASA Form 1 / FAA 8130-3 release; QA acceptance	N/A	Done

4. PARTS LIST

Part No.	Description	Qty	Cond.	Cert. Ref.	Cost
1794M91P01	Fan Blade set (4 replaced)	4	NEW OEM	CFM/BOR2024	USD 42,800
1795M11P01	LPC Blade set Stage 2 (28 blades)	28	NEW OEM	LHT/BOR2025	USD 28,600
1796M01P01	HPC Disc Stage 3 (LLP at limit)	1	NEW OEM	CFM/LLP2025	USD 148,500
1797M03P01	HPT Stage 1 Blade set (80 blades)	80	NEW OEM	LHT/BOR2025	USD 312,400
1797M04P01	HPT Stage 2 Blade (2 blades)	2	NEW OEM	LHT/BOR2025	USD 18,600
HPT-NGV-S1	HPT Stg 1 Nozzle Guide Vane Ring	1	NEW OEM	CFM/NGV2025	USD 89,200
HPT-NGV-S2	HPT Stg 2 Nozzle Guide Vane Ring	1	NEW OEM	CFM/NGV2025	USD 72,100
LPT-NOZ-S4	LPT Stage 4 Nozzle (3 segments)	3	NEW OEM	LHT/BOR2025	USD 34,500
LPT-BLD-MIX	LPT Blades Stages 4–7 (8 blades)	8	NEW OEM	LHT/BOR2025	USD 22,800
BRG-NO3-XX	No. 3 Bearing (LLP at limit)	1	NEW OEM	CFM/BRG2025	USD 8,400
SEL-CRBNS-1	Carbon Seals No.1 Bearing Compartment	3	NEW OEM	LHT/SL2025	USD 4,200
FNZ-20PLCE	Fuel Nozzles (set of 20)	20	NEW OEM	CFM/FN2025	USD 41,600
IGN-PLUG-SET	Igniter Plug Set (2×)	2	NEW OEM	LHT/IG2025	USD 1,800
HVOF-COAT-567	HVOF Coating HPC Stages 5–7	3 stages	PROCESS	LHT/HVOF2025	USD 36,800
MISC-HARDWARE	Hardware (nuts, bolts, seals, gaskets)	Lot	NEW OEM	LHT/MISC2025	USD 12,400

5. LABOUR BREAKDOWN

Activity	Hours	Rate (USD/hr)	Total (USD)
Engine Disassembly & Assembly — Lead Mechanic	284	USD 145	USD 41,180
Module Build Fan/LPC/HPC — Mechanic	312	USD 132	USD 41,184

Hot Section Build HPT/LPT — Mechanic	298	USD 132	USD 39,336
NDT (FPI/UT/Eddy Current)	96	USD 158	USD 15,168
QA Inspection	48	USD 165	USD 7,920
Test Cell Operator (3 runs)	36	USD 145	USD 5,220
Documentation / Certification	24	USD 120	USD 2,880
Overhead (15%)	—	—	USD 23,082
TOTAL LABOUR	1,098 hrs	—	USD 175,970

6. COST SUMMARY AND ELIGIBILITY

Category	Amount	Eligible Account	Eligible?
OEM Parts — HPT/NGV/Fan/Fuel	USD 876,500	Engine Performance	YES
HPC Stage 3 LLP replacement	USD 148,500	Engine LLP	YES
No. 3 Bearing LLP replacement	USD 8,400	Engine LLP	YES
Labour (1,098 hrs)	USD 175,970	Engine Performance	YES
Test Cell (3 runs)	USD 38,500	Engine Performance	YES
Transport (ferry + delivery)	USD 14,200	Engine Performance	YES
Tooling	USD 12,400	Engine Performance	YES
TOTAL CLAIM	USD 1,117,570	—	—
Performance sub-account balance	USD 824,000	—	—
LLP sub-account balance	USD 416,000	—	—
Lessee shortfall	USD 0	—	COVERED

7. SUPPORTING DOCUMENTATION ATTACHED

Ref	Document	Pages
SUPP-01	LHT Shop Visit Work Order WO-LHT-2025-04812	48
SUPP-02	Teardown Inspection Report (TIR)	32
SUPP-03	Build-Up Inspection Report (BIR)	28
SUPP-04	Performance Test Cell Run Report — Runs 1, 2, 3	18
SUPP-05	EASA Form 1 / FAA 8130-3 for all replaced parts	31
SUPP-06	Parts traceability back-to-birth documentation	22
SUPP-07	Updated LLP tracking sheet (post-PRSV)	4
SUPP-08	Updated Engine Logbook pages	8
SUPP-09	Final Invoice — Lufthansa Technik AG	6
SUPP-10	Photo documentation (188 photos)	38
SUPP-11	Pre-PRSV borescope report (Delta TechOps)	14

IN WITNESS WHEREOF the parties have executed this document as of the date first written above.

CLAIMANT (LESSEE)	**LESSOR (APPROVAL)**
By: _____	By: _____
Name: Sarah J. Watkins	Name: Patrick Dunne
Title: VP Technical Operations	Title: Portfolio Technical Manager
Date: 2025-04-10	Date: _____