



Property inspection report

Job reference: **REP-250904-024417** · Priority: Routine · HHSRS pre-screen: yes

Inspection details

Property	Flat 38 Westwood House, Tilman Estate, Lambeth Road, London SE1 7QF
Tenant	Ms Crystal Bello (Tenancy TEN-SWK-2018-04412)
Reported by	C. Bello (tenant), telephone, 04 September 2025
Inspected by	M. Iyer MCIH, Housing Repairs Officer (Staff ID 4042)
Accompanied by	None
Date of inspection	Friday 26 September 2025, 11:15 to 11:40
Reported issue	Damp / mould in children's bedroom and bathroom
Weather at time of inspection	Dry, 17°C, light breeze

Findings

Visible black mould was observed on the upper portion of the south-facing wall in Bedroom 2 (children's bedroom) covering approximately 1.5 m². Further small areas of mould were noted on the bathroom ceiling around the extractor fan housing and behind the WC. The kitchen wall is clean and shows no current evidence of mould growth.

Hygrometer readings (Protimeter Mini): bedroom relative humidity 71% at 19°C; bathroom 84% (post-shower) reducing to 64% after 20 minutes with the extractor on. The bathroom extractor fan ran but exhibited reduced air-flow when tested with a vane anemometer (measured 9 l/s against a required 15 l/s).

External street-level inspection of the south elevation brickwork did not identify any obvious defect. Rainwater goods on the south elevation appear clear from ground observation. No access was obtained to roof level on this visit.

Diagnosis

The cause is provisionally assessed as **condensation due to insufficient ventilation** rather than ingress of water. The combination of elevated indoor relative humidity, restricted bathroom extraction, and the tenant's reported drying of clothing indoors is consistent with this diagnosis. No evidence of penetrating damp was identified during this inspection. A further specialist damp inspection should be considered if the symptoms recur following the recommended remedial works.

HHSRS pre-screen

Hazard 1: Damp and mould growth	Category 1
Hazard 2: Excess cold	Not assessed at this visit
Recommended escalation	Specialist damp inspection if recurrence



Vulnerable occupants

Two children aged 5 and 9 resident at the Property

Recommended works

1. Replace bathroom extractor fan with a higher-rated humidity-sensing unit (Vent-Axia 100T or equivalent).
2. Issue tenant with a portable domestic dehumidifier (Meaco 12L) on temporary loan for 28 days.
3. Treat the visible mould affected areas with a proprietary fungicidal wash; remove and renew any redundant wallpaper.
4. Provide the tenant with the Council's 'Reducing condensation in the home' leaflet.
5. Carry out post-works inspection at 28 days and 90 days with hygrometer readings.

Tenant's comments at inspection

The tenant stated that the walls feel wet to the touch when it has rained heavily and disagreed with the condensation diagnosis. She asked whether the external brickwork could be checked. She advised that her youngest child has been coughing for several weeks.

Signed

Inspecting officer:

M. Iyer

M. Iyer MCIH, Housing Repairs Officer
26 September 2025

Authorised by:

R. Patel

R. Patel, Repairs Team Leader
Approved: 29 September 2025