

Handling Errata in PCB Design

1. We have **vias underneath the Type-C port**, which aren't filled as it would add to the BoM. Add to that we've Grounded the mounting pins to try and protect against ESD. This will have the unintended side-effect of shorting the **USB_D** nets to **GND** via the **Type-C's mounting case**.
 - **Impact:** The Micro Controller **NOT** being visible as a **JTAG interface on HOST/PC**. Worst case damage the HOST/PC's USB Port if it's not protected.
 - **Solution:** Check the continuity between the **Type-C** mounting case, and the **0 Ω** resistors. **Rectify before first boot** if a short is indeed present.