



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/02/2026

Shift: C

Incharge(s): Amit Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------|------------------------------|---|----------|----------|--|
| 1 | OHP | TT-1 | Reported LT not taking place | MPCB tripped.Reset done(2 times) | 23:30:00 | 00:00:00 | |
| 2 | OHP | TT-1 | Reported no power | MPCB tripped in LC-7.CRD cable stuck in roller and cable insulation damaged. rejoint done and tested okay | 03:15:00 | 04:00:00 | |
| 3 | OHP | TBS on CO-5A | LT not taking place | PCRD tension acted.Released and tested okay | 03:55:00 | 04:15:00 | |
| 4 | OHP | CO-34 | Reported tripped | OLR acted.Reset done(2 times) | 04:35:00 | 04:46:00 | |
| 5 | CHP | Cc-51 | MPD tripped | Reset done(2 times) | 00:55:00 | 03:00:00 | |
| 6 | CHP | CC-117 | Reported tripped | OLR acted.Reset done | 01:02:00 | 01:22:00 | |
| 7 | CHP | CC-51 | ZSS acting | Cage problem.Replaced and tested okay | 22:45:00 | 23:15:00 | |
| 8 | CHP | CC-37 SCR-3 | ZSS acting | Cage stuck with coal.Replaced but pulse found missing.Bypassed to minimize GPL delay | 22:25:00 | 22:35:00 | Probe to be checked and to be replaced |
| 9 | CHP | Cc-218 | CJD acted | Probe cleaned and tested okay | 23:20:00 | 23:30:00 | |
| 10 | CHP | Cc-32 S-3 | Slewing not taking place | 30 degree limit acted. | 00:25:00 | 00:40:00 | |
| 11 | CHP | Cc-104 SCR-7 | LT not taking place | PCRD tension acted.Released and tested okay(4 times) | 01:00:00 | 04:25:00 | |
| 12 | CHP | Cc-216 | CJD acted. | Probe cleaned and tested okay | 01:45:00 | 01:55:00 | |
| 13 | CHP | Cc-213 | CJD acted. | Probe cleaned and tested okay | 01:55:00 | 02:15:00 | |
| 14 | CHP | CC-14 | Control MCB tripped | CJB cable found loose and getting earthed.Tightened and tested okay | 01:40:00 | 02:00:00 | |



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/02/2026

Shift: C

Incharge(s): Amit Roy

| SI No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------|---------|---|----------|----------|---------|
| 15 | WT | OT-3 | Tripped | D-1 tripped on Encoder-43 fault. Encoder cables at JB found damaged. Cable rejoint done and tested okay | 23:40:00 | 00:40:00 | |