



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/12/2025

Shift: A

Incharge(s): Amit Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------|------------------------------|--|----------|----------|--------------------------------------|
| 1 | OHP | TT-1 | LT not taking place | MPCB tripped.Made on and tested okay | 07:25:00 | 07:35:00 | |
| 2 | OHP | AF-4 | Reported tripped | Drive tripped on speed deviation.Reset done | 12:00:00 | 12:10:00 | |
| 3 | OHP | CO-44 hoist | Reported not working | MCCB tripped in Lc-6 due to overload.Made on. | 10:00:00 | 10:10:00 | |
| 4 | OHP | WOBR on CO-25 | Reported LT not taking place | Brakes adjusted by mechanical and track jamming cleared | 10:40:00 | 11:00:00 | |
| 5 | OHP | BRC on CO-8A | Reported CT not taking place | Drive tripped.Reset done | 13:30:00 | 13:40:00 | |
| 6 | CHP | Cc-21 | ZSS cage damaged | Replaced and tested okay | 07:30:00 | 07:45:00 | |
| 7 | CHP | CC-51 | Reported tripped | MPD tripped.Feeding conveyor stopped.Reset done(7 times) | 07:00:00 | 13:00:00 | |
| 8 | CHP | CC-54 | Reported tripped | OLR acted due to offcentering and over feeding.Reset done(6 times) | 07:50:00 | 08:20:00 | Informed to operation and mechanical |
| 9 | CHP | CC-104 SCR-9 | Reported luff not working | OLR acted.Reset done | 10:18:00 | 10:25:00 | |
| 10 | WT | OT-1 | Reported tripped | D1 tripped on PGEF fault.Reset done | 08:25:00 | 08:30:00 | |