

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 10/09/2025

Shift: A

Incharge(s): K SANKARA RAO

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|-------------------------|--|---|----------|----------|---------|
| 1 | OHP | WOBR ON CO-29 | B/C STOPPING ON ZSS CHECKED ZSS PROBE DAMAGED | ZSS PROBE REPLACED THAN OK | 07:00:00 | 07:20:00 | |
| 2 | OHP | CO-25 | REPORTED STOPPING ON ZSS CHECKED ZSS PROBE DAMAGED | ZSS PROBE REPLACED WITH NEW PROBE THAN OK | 09:00:00 | 09:15:00 | |
| 3 | OHP | BF-2A | FREQUENTLY STOPPED CHECKED AND FOUND ZSS PROBE LOOSE | ZSS PROBE PROPERLY FIXED THAN OK | 07:40:00 | 07:50:00 | |
| 4 | OHP | BRC ON CO 34 | LT NOT TAKING PLACE CHECKED PCRD O/T ACTED | RELEASED THAN LT OK | 10:00:00 | 10:20:00 | |
| 5 | CHP | CC-131 | OLR ACTED | RESET DONE | 07:40:00 | 07:50:00 | |
| 6 | CHP | CC-51 | OLR ACTED DUE TO FEEDING CONVEYOR STOP | RESET DONE | 09:50:00 | 10:00:00 | |
| 7 | CHP | CC-29 | OLR ACTED | RESET DONE | 06:15:00 | 06:22:00 | |
| 8 | CHP | CC-22 (B/D) | OLR ACTED | RESET DONE | 07:00:00 | 07:10:00 | |
| 9 | CHP | CC-22 | C/S NOT HEALTHY | C/S CLEANED THAN OK | 07:15:00 | 07:25:00 | |
| 10 | CHP | CC-104 AND CC-105 | NOT RUNNING BRS SUPPLY TRIPED IN CM-16 I/O RACK MCB | MCB MADE ON | 06:00:00 | 07:00:00 | |
| 11 | CHP | CC-37 SCR-7 | LT NOT TAKING PLACE PCRD O/T ACTED | RELEASED THAN OK | 08:20:00 | 08:30:00 | |
| 12 | СНР | CC-37 SCR-7 | B/C NOT RUNNING CHECKED C/S ACTED DUE TO WET COAL | AFTER MATERIAL CLEANED THAN OK | 08:50:00 | 09:20:00 | |
| 13 | CHP | CC-104 SCR-9 | SLEW NOT WORKING MPR TRIP | RESET DONE THAN OK | 10:50:00 | 11:00:00 | Pag |



RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 10/09/2025

Shift: A

Incharge(s): K SANKARA RAO

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|-----------------|--|---------------------|----------|----------|---------|
| 14 | CHP | CC-125 CC-44 | OLR ACTED | RESET DONE | 11:05:00 | 11:10:00 | |
| 15 | CHP | CC-40 SCR-3 | LT NOT TAKING PLACE PCRD O/T ACTED | RELEASED THAN OK | 11:10:00 | 11:20:00 | |
| 16 | CHP | CC-37 SCR-7 | LT NOT TAKING PLACE DRIVE TRIP DUE TO TRACK JAMMING | RESET DONE | 12:15:00 | 12:20:00 | |
| 17 | WT | OP-9 | REPORTED NOT MOVE F/R CHECKED AND FOUND ACB TRIP IN LC-10B | ACB MADE ON THAN OK | 10:20:00 | 10:30:00 | |
| 18 | WT | CO-4 (B/D) | MPCB TRIP | RESET DONE | 10:40:00 | 10:50:00 | |