



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 18/01/2026

Shift: B

Incharge(s): Amit Roy

| SI No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|------------------|-----------------------------------|--|----------|----------|-------------------------------------|
| 1 | OHP | BRC on CO-28 | CT not taking place | Wrong complaint | 15:00:00 | 15:20:00 | |
| 2 | OHP | BRC on CO-33M | LT not taking place | PCRD tension acted. Released and tested okay | 19:00:00 | 19:10:00 | |
| 3 | OHP | Stacker on CO-21 | Reported left luff tripping | Mechanical gearbox problem | 16:10:00 | 16:40:00 | Informed to operation |
| 4 | OHP | VF-2A | Reported motor base bolts missing | Bolts replaced(2 times) and found motor tripping on OLR. motor checked and found okay but motor-1 side tray material not moving freely | 18:08:00 | 21:25:00 | Mechanical side checking to be done |
| 5 | CHP | CC-29 | Reported tripped | OLR acted. Reset done | 21:25:00 | 21:30:00 | |
| 6 | CHP | CC-107 | Reported tripped | OLR acted. Reset done | 16:15:00 | 16:20:00 | |
| 7 | CHP | CC-39 SCR-6 | Slew not working | Slew area coal jamming | 20:50:00 | 21:00:00 | Informed to operation |
| 8 | WT | OP-2,3,6 | Reported not moving | Communication problem. PLC power recycled. | 15:10:00 | 15:25:00 | |
| 9 | IOSA | BRC | LT not taking place in auto | B/W-1 OLR acted. Reset done | 20:00:00 | 20:15:00 | |