



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/12/2025

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-------------|--|--|----------|----------|----------------------|
| 1 | OHP | CC 58 | control tripped due to earth fault in PC | PC isolated and bypassed | 18:30:00 | 18:45:00 | PC to be checked |
| 2 | OHP | CO 26 | OLR acted | reset | 14:20:00 | 14:30:00 | 3 times |
| 3 | OHP | CO 85 | olr acted | reset | 17:20:00 | 17:30:00 | |
| 4 | OHP | CO 25 | olr acted | reset | 18:30:00 | 18:40:00 | |
| 5 | CHP | cc 26 | zss module problem | probe replaced, zss bypassed | 17:00:00 | 17:12:00 | module to be changed |
| 6 | CHP | CC 37 scr 7 | b/c not running,mpd tripped | reset | 18:30:00 | 18:40:00 | |
| 7 | CHP | CC 33 R1 | luffing not working,olr acted | reset | 20:30:00 | 20:45:00 | |
| 8 | WT | OP 10 | no movement,D3,b phase got melt | d3 power made off and bypass in SCADA system | 16:40:00 | 17:10:00 | |
| 9 | WT | OP 10 | no movement,D1,D4,D5 healthy not coming,after some time all drive healthy not coming,PLC problem | communication checked,control checked found all drive OK not coming,made high in logic and LCS rev continuous made force low,checked and found lcs REV contact problem | 19:10:00 | 19:55:00 | |