



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/05/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 29	olr acted	reset	22:00:00	22:10:00	
2	OHP	wobr on Co6A	slew not working,cp acted	informed mechanical	01:00:00	01:10:00	
3	OHP	BRC on CO 28	no power,power is there,LT not working, main interlock mcb was in off	brake fuse replaced,mcB made on	05:55:00	06:30:00	
4	OHP	brc on co 34	B/W 2 not running,timer problem,loose connection	panel is full of dust tracing of cable is impossible,T1,T2,T3,T4 identification problem,T1 timer control wire loose connection tightened,Bw 2 bypassed given temporary clearance	05:25:00	06:30:00	refereed to a shift
5	OHP	CO 36	olr acted	reset	00:40:00	00:50:00	
6	CHP	CC 39 SCR7	LT not working,drive tripped	reset	22:30:00	22:40:00	
7	CHP	cc 39 scr 7	b/c not running in stacking mode,slew limit problem,magnet switch cable opened	first bypassed than magnet cable rejoined	22:40:00	23:00:00	
8	CHP	CC 37 scr 3	LT not working,m3 tripped	made it on	04:53:00	05:00:00	
9	CHP	CC 51	mpd acted	reset	23:40:00	23:45:00	2 times
10	CHP	CC 58 TT	power cable got cut,position sensor not coming	rejointed power cable,tt position sensor bypassed in I/o rack	01:10:00	03:00:00	