



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 16/05/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment                | Problem                                                                                                  | Action                                                                                                  | From     | To       | Remarks |
|-------|------|--------------------------|----------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|----------|----------|---------|
| 1     | OHP  | CO 26                    | olr acted                                                                                                | reset                                                                                                   | 18:15:00 | 18:25:00 |         |
| 2     | OHP  | TBS on CO 24             | LT not working,M4 and M2 tripped                                                                         | reset                                                                                                   | 21:40:00 | 21:55:00 |         |
| 3     | OHP  | CO 13(B)                 | OLR acted                                                                                                | reset                                                                                                   | 17:50:00 | 17:55:00 |         |
| 4     | OHP  | TIS on CO 29             | ZSS acted ,due to mechanical problem                                                                     | informed to mech                                                                                        | 20:20:00 | 20:30:00 |         |
| 5     | OHP  | BF5A                     | not running,stopping in ZSS,belt is slow moving due to jamming                                           | run in local and than PLc ok                                                                            | 16:45:00 | 17:10:00 |         |
| 6     | CHP  | cc 105 scr 10            | all drive not working,PLc in stop mode,wireless no communication,24V dc loose connection for analog card | PLC change from stop mode to RUN mode,wireless cable unplugged and plugged,24 V dc +ve tightened in MCB | 19:45:00 | 21:00:00 |         |
| 7     | CHP  | CC 104 scr6              | slew not working,coal jamming                                                                            | informed operation                                                                                      | 20:00:00 | 20:15:00 |         |
| 8     | CHP  | CC 33 scr2               | complaint ,b/c not running                                                                               | 30 degree slew not coming,magnetic switch position done                                                 | 17:45:00 | 18:00:00 |         |
| 9     | CHP  | CC 52 TIS and CC 130 TIS | mcb tripped in l/o rack                                                                                  | 52 TIS is in off and 130 TIS kept in on                                                                 | 19:44:00 | 20:15:00 |         |