



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 10/09/2026

Shift: A

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR ON CO-29	REPORTED LT NOT TAKING PLACE FOUND PCRD O/T NOT HEALTHY LIMIT SWITCH INSIDE ONE WIRE OPENED	WIRE RE-CONNECTED THAN OK	06:25:00	06:45:00	
2	OHP	BRC ON CO-28	B/C OLR ACTED DUE TO MATERIAL OVER LOAD	RESET DONE AND INFORMED TO OPERATION	07:15:00	07:25:00	
3	OHP	TBS ON CO-21	REPORTED LT NOT TAKING PLACE PCRD O/T ACTED DUE TO PCRD DRUM NOT ROTATING FOUND PCRD PANEL TIMER CONTACT WIRE LOOSE	PROPERLY TIGHT THAN OK	07:30:00	07:50:00	
4	OHP	TBS ON CO-22	PCRD CABLE OVER LAPPING DUE TO GUIDE PROBLEM	PCRD CABLE PROPER LAYING WAS DONE WITH MECHANICAL	09:30:00	10:15:00	
5	OHP	CO-34	OLR ACTED	RESET DONE	09:25:00	09:30:00	
6	OHP	HVMCC-4	ALL CONVEYORS NOT HEALTHY	IC-1 TRIPPED ON UNDER VOLTAGE AND ALSO IC-1 TRIPPED IN LBDS-8 ON OVER CURRENT.BOTH IC'S MADE ON AND TESTED OKAY	08:48:00	09:10:00	
7	WT	OP-6	REPORTED NOT MOVE FOUND E/STOP ACTED (DEAD-END)	RELEASED THAN OK	07:35:00	07:45:00	
8	WT	OT-5	OUT-HALL SIDE INITIAL SENSOR FREQUENTLY ACTED	INITIAL SENSOR BYPASSED	10:45:00	11:00:00	